



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/06/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- SLE97C

Veh Model :- BMW 318i SEDEN

Estimate# :- CK421943

Claim # :-

ACC. Date :- 08/06/21

Terms :- C.O.D Days

Remarks :-

CK141239

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR DOOR LH <i>4</i>	1	PC	1,380.20	1,380.20
2.	REAR DOOR WEATHERSTRIP LH <i>me</i>	1	PC	155.15	155.15
3.	REAR DOOR GLASS REGULATOR LH <i>7. xsn</i>	1	PC	253.95	253.95
4.	REAR DOOR GLASS REGULATOR MOTOR LH <i>7. xsn</i>	1	PC	323.80	323.80
5.	REAR DOOR INNER TRIM LH - CHECK <i>7. xsn</i>	1	PC		
6.	ROCKER PANEL GARNISH LH <i>sch</i>	1	PC	388.90	388.90
7.	REAR FENDER LH (REPAIR) <i>R</i>	1	PC		
8.	REAR BUMPER <i>sch</i>	1	PC	1,332.85	1,332.85
9.	REAR BUMPER RETAINER LH <i>+ sch</i>	1	PC	60.05	60.05
10.	REAR FORK RIM - CHECK <i>(SPORT) sch</i>	1	PC		
11.	REAR WHEEL BEARING - CHECK <i>? me</i>	1	PC		
12.	REAR SHOCK ABSORBER LH - CHECK <i>? 4</i>	1	PC		

LIST TOTAL S\$

5% DISCOUNT S\$

REAR KNUCKLE ARM LH - 1112.50

REAR LOWER ARM LH - 352.50

REAR WHEEL BEARING Hub LH - 166.40

LABOUR :

TO KNOCK AND STRAIGHTEN REAR FENDER LH,
ROCKER PANEL LH. REMOVE & REPLACE ACCIDENT
DAMAGED PARTS, REALIGN ALL CONNECTION

SPRAY PAINT REAR DOOR LH, ROCKER PANEL
GARNISH LH, REAR FENDER LH, ROCKER PANEL LH
REAR BUMPER

REMOVE & REPLACE REAR DOOR INNER TRIM,
MECHANISM AND CHECK LOCKING SYSTEM

RUST PROOF AFFECTED AREAS

DIAGNOSE AND RESET SYSTEM AFTER REPAIR

REMOVE & REPLACE REAR UNDERCARRIAGE LH SIDE

LABOUR TOTAL S\$

5112.71

500.00

1490.00

7102.71

20%

5682.16

45-5,650

6 days

450
500.00

700 800.00

60
80.00

30.00

150 200.00

100 150.00

1,760.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang
Singapore 159415
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008
Bukit Merah Lane 3
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033C
GST Reg. M2-0088864-2

Estimate

09/06/2021

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 141239

Veh # :- SLE97C

Veh Model :- BMW 318i SEDEN

Estimate# :- CK421943

Claim # :-

ACC. Date :- 08/06/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,460.15

GST @ 7 % 382.21

AMOUNT DUE S\$ 5,842.36

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hy 20010068
6 days
4/5
10/06/21 @ 1540
Resy after repair

Required alignment
copy