

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

YEO AH HEE
BLK 589D MONTREAL DRIVE
#04-124
S 754589

TPAXA
Justin.

Vehicle no :SH 2807 J
Make/Model :TOYOTA AXIO
Accident date :09.06.2021

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

List Items

1	Rear bootlid <i>Buckled</i>	1	\$ 753.30 ✓
2	Rear bootlid hinges @ \$106.40 <i>new</i>	2	\$ 212.80 +
3	Rear bootlid upper lock <i>Damaged</i>	1	\$ 103.70 ✓
4	Rear bootlid lower lock <i>new</i>	1	\$ 24.30 +
5	Rear bootlid weather strip <i>lit</i>	1	\$ 263.70 ✓
6	Rear bootlid handle <i>new</i>	1	\$ 230.70 X.
7	Rear bootlid centre logo	1	\$ 64.70 ✓
8	Rear bootlid COROLLA emblem <i>new</i>	1	\$ 43.10 ✓
9	Rear bootlid AXIO emblem	1	\$ 46.80 ✓
10	Rear bootlid insulation <i>new</i>	1	\$ 218.10 +.
11	Rear end panel <i>Dented</i>	1	\$ 662.30 ✓
12	Rear end panel inner top garnish <i>crushed</i>	1	\$ 240.80 ✓
13	Rear bumper <i>Deformed</i>	1	\$ 477.20 ✓
14	Rear bumper side holder @ \$99.80 <i>new</i>	2	\$ 199.60 85.
15	Rear bumper reflector @ \$59.50 <i>new</i>	2	\$ 119.00 X.
16	Rear lamp @ \$413.00 <i>crushed</i>	2	\$ 826.00 700
17	Rear lamp housing @ \$157.40 <i>Repair</i>	2	\$ 314.80 X
18	Rear lamp housing bracket @ \$99.50 <i>new</i>	2	\$ 199.00 X
19	Rear fender inner trim @ \$346.60 <i>torn</i>	2	\$ 693.20 ✓
20	Rear fender inner shield @ \$62.60 <i>new</i>	2	\$ 125.20 +
21	Rear fender @ \$880.10 <i>new</i>	2	\$ 1,760.20 880.10
22	Rear spare tyre top board <i>Deformed</i>	1	\$ 567.40 325
23	Rear spare tyre well <i>Repair</i>	1	\$ 701.60 X
24	Rear spare tyre well insulation @ \$424.20 <i>new</i>	3	\$ 1,272.60 X.
			\$ 10,120.10
Less 25% Disc			\$ 2,530.03
Total			\$ 7,590.08

Special Nett Items

1	Rear bumper reverse sensor (1 set) <i>Damaged</i>	1	\$ 380.00 200
2	Rear bumper clips (1 set) <i>new</i>	1	\$ 60.00 30.
Total			\$ 440.00

230

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

YEO AH HEE
BLK 589D MONTREAL DRIVE
#04-124
S 754589

Vehicle no :SH 2807 J
Make/Model :TOYOTA AXIO
Accident date :09.06.2021

No	Description	Qty	Amount (\$\$)
Labour Cost			
1	To supply rear end panel inner sealant		\$ 200.00 60.
2	Remove & reinstall exhaust pipe		\$ 150.00 +.
3	Remove & reinstall reverse sensor		\$ 150.00 50.
4	Remove & reinstall bootlid inner garnish	2430	\$ 200.00 60.
5	Remove,replace & repair consistent to the accident		\$ 1,900.00 1200.
6	Respray painting		\$ 1,600.00 1000.
7	Tuff kote		\$ 150.00 60.
Total			\$ 4,350.00
Grand Total			\$ 12,380.08

Total: 6664.17

L/s: 5.3k

08Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: