

SBR173R

Toyota Camry 1998cc

MR053BK4107025258

TP AxA.

Denise.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Front Bumper	Deformed	565.10	✓
Front Bumper Clips.	Neu	30	✓
Front Bumper Side Holder x 02	RH cracked	54.90	
		$54.9 \times 2 = 109.80$	
Front Bumper Fog Lamp RH	Cracked	298.80	✓
Front Bumper Fog Lamp Cover RH	Neu	60.80	x
Front Bumper Chrome Moulding RH	Cr	134.60	✓
Front Bumper Reinforcement.	Neu	374.50	x
Front Grille		382.30	x
Front Grille Logo	Not NEC	61.10	x
Front Grille Clips.		20	x
Front RH Fender	Distorted	731.30	✓
Front RH Fender Inner Shield	Deformed	201.50	✓
Front RH Fender Inner Shield Clips.	Neu	30	✓

SBR173R.

Handling RH. *cancelled* 1395 ✓

Front RH Door Wing Mirror *RHS* 971.10 X

Front RH Wheel Rim. *cut* ~~880(SN)~~ ~~450(SN)~~

Front RH Tyre. *Xbe rec* 300(SN) X

Front RH Lower Arm. *2* 494.10 X

Front RH Knuckle Arm. *2* *NH* *Nec* 561.60 X

Front RH Wheel Hub *clw* Bearing *2* 240.60 X

Front RH Shock Absorber. *2* *NH* *rec* 399.50 X.

3441.20

2580.9

SN: 450.

Panel Beating

~~1000~~ 500

Spray Painting. 1110.

~~800~~ 500

Wiring.

~~50~~ 30

To perform wheel alignment.

~~150~~ 80

To dismantle front undercarriage. 350 X

total: 4140.90

\$10.591.70

L/S: 3.3K. OADays