

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305472734  
Date : 14/06/21

## FINALIZATION FORM

To : LKK  
Attn : NAZ  
Vehicle Reg No. : SHA9369C

Fax :  
08/06/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: NTUC GBG7540B

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_


(c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$3,000.00


3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : CHIANG  
Tel : 62148314  
Fax : 65468156

Signature :   
Name : NAZ LKK  
Date : 16/6/2021

### For Official Use Only

| Item   | Amount        | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|---------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |               | YES                         |                        |         |
| 2. Loss of Income Paid                               | -             | N                           |                        |         |
| 3. Survey Fees                                       | -             | -                           |                        |         |
| 4. LTA Search Fee                                    | \$7.49/\$2.00 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |               |                             |                        |         |
| 6. Overrun   |               |                             |                        |         |

Remarks:

\_\_\_\_\_

\_\_\_\_\_

REPAIR ESTIMATE\*

VEHICLE NO SHA9369C

07/06/21

MAKE :

MODEL I-40

CHIANG /NTUC

| Qty | Parts Description/ Labour            | Type | Unit Price | Amount            |
|-----|--------------------------------------|------|------------|-------------------|
| 1   | FRONT BUMPER BRACKET RH              |      |            | \$24.60           |
| 1   | FRONT BUMPER TOP BRACKET RH          |      |            | \$22.40           |
| 1   | FRONT BUMPER                         |      |            | \$1,052.20        |
| 1   | FRONT BUMPER GRILLE RH               |      |            | \$187.20          |
| 1   | RADIATOR GRILLE                      |      |            | \$1,480.00        |
| 1   | FRONT FENDER RH                      |      |            | \$663.00          |
| 1   | FRONT FENDER SHIELD /RH              |      |            | \$174.90          |
| 1   | HEAD LAMP ASSY RH                    |      |            | \$1,800.00        |
| 1   | HEAD LAMP SUPPORT PANEL              |      |            | \$907.40          |
| 1   | FRONT WHEEL CAP RH                   |      |            | \$217.20          |
| 1   | FRONT ENGINE UNDER COVER             |      |            | \$334.60          |
| 10  | BUMPER CLIPS                         |      | \$2.20     | \$22.00           |
|     | <b>SUB TOTAL</b>                     |      | 3266.30    | <b>\$6,885.50</b> |
|     | <b>LESS 20%</b>                      |      | 2,613.04   | <b>\$1,377.10</b> |
|     |                                      |      |            | <b>\$5,508.40</b> |
|     | <b>Labour Charge</b>                 |      |            |                   |
|     | Panel Beating                        |      |            | \$840.00          |
|     | Spray Painting Charge                |      |            | \$750.00          |
|     | Remove/refix air con & charge in gas |      |            | \$120.00          |
|     | Tuff Kote                            |      |            | \$60.00           |
|     | Check Lighting                       |      |            | \$60.00           |
|     | <b>TOTAL LABOUR</b>                  |      | 3,743.04   | <b>\$1,830.00</b> |
|     | <b>ESTIMATE TOTAL</b>                |      |            | <b>\$7,338.40</b> |

?XSVL  
?XSVL  
/CRK  
?XSVL  
XSVL  
XR  
/DEF  
/SCR  
XSVL  
/SCR  
?XSVL  
/NEU

560  
500  
XNN  
40  
30

NAZ CLK  
9/16/2021 155  
3 DAYS  
LIS  
CHECK ITEM PHOTOS  
AFTER REPAIR PHOTOS

**LKK Auto Consultants** hence hereby  
the Repairer of the following:

- To resurvey before spray painting
- To display car to customer for resurvey
- Parts price based on the quotation
- Third party survey on "without prejudice" basis
- No hidden charges
- Subject to the terms and conditions of the insurance policy

Acknowledged by Repairer  
Signature:  
Date: