

**COMFORTDELGRO PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO **SHA9369C**

07/06/21

MAKE :

MODEL **I-40**

**CHIANG /NTUC**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH			\$24.60
1	FRONT BUMPER TOP BRACKET RH			\$22.40
1	FRONT BUMPER			\$1,052.20
1	FRONT BUMPER GRILLE RH			\$187.20
1	RADIATOR GRILLE			\$1,480.00
1	FRONT FENDER RH			\$663.00
1	FRONT FENDER SHIELD /RH			\$174.90
1	HEAD LAMP ASSY RH			\$1,800.00
1	HEAD LAMP SUPPORT PANEL			\$907.40
1	FRONT WHEEL CAP RH			\$217.20
1	FRONT ENGINE UNDER COVER			\$334.60
10	BUMPER CLIPS		\$2.20	\$22.00
	<b>SUB TOTAL</b>			<b>\$6,885.50</b>
	<b>LESS 20%</b>			<b>\$1,377.10</b>
				<b>\$5,508.40</b>
	<b>Labour Charge</b>			
	Panel Beating			\$840.00
	Spray Painting Charge			\$750.00
	Remove/refix air con & charge in gas			\$120.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,830.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$7,338.40</b>

?  
?  
/ CLK  
?  
XSVL  
XR  
/ DEF  
/ SCR  
XSVL  
/ SCR  
?  
/ NEW

560  
500  
XNN  
40  
30

NAZ CLK  
9/6/2021 155  
3 DAYS  
LIS  
CHECK ITEM PHOTOS  
AFTER REPAIR PHOTOS

**LKK Auto Consultants** hence certify  
the Repairer of the following:

- To resurvey before spray painting
- To display a name tag during resurvey
- Parts price is based on the estimation
- Third party involvement on a "no prejudice" basis
- No hidden charges
- Supplemental work is to be used and is subject to prior approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date: