		COMFORTDELGRO				
Our Job Ref No :	305472895		i	ENGINEERING		
Date : 10/06/21		ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969				
FINALIZATION FORM			F	ax: 6546 8156		
To : LKK			Fax	:		
Attn : Mr	NAZ					
Vehicle Reg No. : SI	HC8276H CTPL			10.06.21		
_	of the repairs of the above-m	entioned vehic	le are as follo	ws:-		
The repair job shall		NTUC		FBP3710G		
2. The finalized amou						
	after List discount					
(b) Labour Char	_					
lotal for Pa	rt-By-Part Repair Cost					
Total for Lum	epair (if applicable) opsum repair cost after Less: sum Repair cost	20%	6	\$1,750.00		
 Estimated normal potential. We shall treat the aworking days 	eriod for repairs:above amount as Correct and		orking days.	eply from you within 7		
5. Thank you for your assistance.		We confirm the estimates and finalized amount				
Signature :		Si	onature :	14		
Name : MS. LOKE YY		— Na	Name : NAZ LKK			
Tel : 62148355		— Da	Date : 16/6/2021			
Fax : 654681		_	_			
For Official Use Only						
item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks		
Rental Rate P/Day		YES				
Rental Rate P/Day Loss of Income Paid		NO				
3. Survey Fees						

\$7.49 / \$2.00

LTA Search Fee
 Medical Fees (on behalf of driver, if applicable)

6 Overrun

Remarks:

Sheet2

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC8276H

Make : HYUNDAI

Model : I-40

Date: 10/06/2021

Insurance: NTUC

MVA: MS. LOKE YY

			BURN LINES TO STATE OF THE STAT	NAME OF TAXABLE PARTY OF TAXABLE PARTY.	1
Qty	Parts Description / Labour	Туре	Unit Price	Amount	1 CR
	1 REAR BUMPER COVER			\$1,106.00	
	1 REAR BUMPER CLIPS			\$22.00	/NE (
1 REAR BUMPER SIDE BRACKET RH				\$35.60	? XSVC
	I			\$32.00	> X2NC
	1 REAR BUMPER REFLECTOR LAMP (LH			\$697.80	A/CF
	1 TAIL LAMP AH				
			101500	\$1,893.40	
	SUB TOTAL		(1022.00	\$378.68	
	LESS 20%		1,460.64		
	DISCOUNTED TOTAL		1,760.69	\$1,514.72	
				\$50.00	- NEC
	1 REAR BUMPER ADVERTISEMENT STICKER			\$100.00	/NEU
	1 REARFENDER ADVERTISEMENT STICKER RH				
				\$150.00	
	Labour Charge				XNN
	WIRING CHARGE			\$60.00	40
TUFF KOTE				\$60.00	
PANEL BEATING				280 \$350.00	
	SPRAY PAINTING CHARGE		250	\$500.00	2
	TOTAL LABOUR			\$970.00	
	ESTIMATE TOTAL			\$2,634.72	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NG2 488 194 1016/2021 1530 3 DAYS CHECK 17EN PHOTOS AFTER LEPAR PHOTOS

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- Tiresurvey betters/after spray painting
- To display dama, editor(s) during resurvey
- · Parts prices are subject to confirmation.
- Third porty summer is to a "Without Srepidice" basis with two contents and so its sorts of
- one notice to some stree delives trandice subjection.

of the con

Si

-