

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8276H

Date: 10/06/2021

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE YY

| Qty | Parts Description / Labour | Type | Unit Price | Amount |
|-----|-------------------------------------|------|------------|-------------------|
| 1 | REAR BUMPER COVER | | | \$1,106.00 |
| 1 | REAR BUMPER CLIPS | | | \$22.00 |
| 1 | REAR BUMPER SIDE BRACKET RH | | | \$35.60 |
| 1 | REAR BUMPER REFLECTOR LAMP RH | | | \$32.00 |
| 1 | TAIL LAMP RH | | | \$697.80 |
| | SUB TOTAL | | | \$1,893.40 |
| | LESS 20% | | | \$378.68 |
| | DISCOUNTED TOTAL | | | \$1,514.72 |
| 1 | REAR BUMPER ADVERTISEMENT STICKER | | | \$50.00 |
| 1 | REARFENDER ADVERTISEMENT STICKER RH | | | \$100.00 |
| | | | | \$150.00 |
| | Labour Charge | | | |
| | WIRING CHARGE | | | \$60.00 |
| | TUFF KOTE | | | \$60.00 |
| | PANEL BEATING | | | \$350.00 |
| | SPRAY PAINTING CHARGE | | | \$500.00 |
| | TOTAL LABOUR | | | \$970.00 |
| | ESTIMATE TOTAL | | | \$2,634.72 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

N42 CLK
10/6/2021 1530
3 Days
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis

advised to the repairer

Sir