

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel: 67556142 Fax: 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(GBB4643J)
Policy No:		Date of Loss:	10/06/2021
Vehicle Reg. No.:	SLP7658E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NG KHOON HO	Driver (Insured):	LIM TEO KEE
Make/Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Vehicle Reg. Date:	16/06/2017
Vehicle Colour:	GREY	Chassis No:	JM6BN22A8H0153234
Engine No:	P520444932		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		

Not Authorized
Penalty B4pam
@ 6117.00
9 days

Description of Accident/Loss: REFER TO GIA REPORT ATTACHED.

Remarks: VEHICLE LYING AT YISHUN WORKSHOP

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

COST OF CLAIMS

Parts	
Miscellaneous Items	
Labour	
Paintwork Labour	
Towing	

Acknowledged by Repairer	Amount
Signature:	3,498.00
Date:	590.00

4,080.00

0.00

0.00

Gross Total (S\$) **8,168.00**

+ GST 7.00% (S\$) 571.76

Nett Amount (S\$) **8,739.76**

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 11 Jun 2021)

Parts: 143

MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP7658E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC REAR BUMPER	Ry 0.00	0.00	*390.00F	✓
2	1		*1 PC REAR BUMPER REINFORCEMENT	Ry 0.00	0.00	*210.00F	✓
3	1		*2 PCS REAR BUMPER TOW COVERS @12/PC	N/A 0.00	0.00	*24.00F	✓
4	1		*2 PCS REAR BUMPER REFLECTORS @25/PC	Sm 0.00	0.00	*50.00F	✓
5	1		*2 PCS REAR BUMPER REVERSE SENSORS @90/PC	As per spec 0.00	0.00	*180.00F	✓
6	1		*6 PCS REAR BUMPER CLIPS @2/PC	As per spec 0.00	0.00	*12.00F	✓
7	1		*1 PC REAR BOOT	Ry 0.00	0.00	*420.00F	✓
8	1		*1 PC REAR BOOT LOGO	As per spec 0.00	0.00	*23.00F	✓
9	1		*1 PC REAR BOOT EMBLEM (MAZDA 3)	As per spec 0.00	0.00	*18.00F	✓
10	1		*1 PC REAR BOOT EMBLEM (SKYACTIV)	As per spec 0.00	0.00	*18.00F	✓
11	1		*1 PC REAR BOOT INNER LOCK	As per spec 0.00	0.00	*95.00F	✓
12	1		*2 PCS REAR BOOT REFLECTORS @135/PC	o/s Bux N/A 0.00	0.00	*270.00F	✓
13	1		*1 PC REAR BOOT INNER RUBBER	N/A 0.00	0.00	*80.00F	✓
14	1		*1 PC REAR BOOT NUMBER PLATE LAMP	As per spec 0.00	0.00	*20.00F	✓
15	1		*2 PCS REAR BOOT HINGES @68/PC	R 0.00	0.00	*136.00F	✓
16	1		*2 PCS TAILLAMPS @185/PC	o/s Bux N/A 0.00	0.00	*370.00F	✓
17	1		*1 PC REAR CENTRE PANEL	Ry 0.00	0.00	*210.00F	✓
18	1		*1 PC REAR CENTRE PANEL INNER TOP GARNISH	As per spec 0.00	0.00	*55.00F	✓
19	1		*1 PC REAR SPARE TYRE HOLDER	Sm 0.00	0.00	*38.00F	✓
20	1		*8 PCS REAR BOOT INNER SPONGE CLIPS @3/PC	As per spec 0.00	0.00	*24.00F	✓
21	1		*1 PC FRT BUMPER	Ry 0.00	0.00	*350.00F	✓
22	1		*1 PC FRT BUMPER REINFORCEMENT	R 0.00	0.00	*195.00F	✓
23	1		*1 PC FRT BUMPER LH SIDE RETAINER	As per spec 0.00	0.00	*12.00F	✓
24	1		*7 PCS FRT BUMPER TOP CLIPS @3.5/PC	As per spec 0.00	0.00	*24.50F	✓
25	1		*7 PCS FRT BUMPER TOP CLIPS SMALL @2.5/PC	As per spec 0.00	0.00	*17.50F	✓
26	1		*1 PC FRT GRILLE	As per spec 0.00	0.00	*68.00F	✓
27	1		*1 PC FRT GRILLE LOGO	As per spec 0.00	0.00	*32.00F	✓
28	1		*1 PC FRT GRILLE MOULDING	As per spec 0.00	0.00	*85.00F	✓
29	1		*2 PCS FRT GRILLE CLIPS @18/PC	As per spec 0.00	0.00	*36.00F	✓
30	1		*1 PC FRT NUMBER PLATE GARNISH	As per spec 0.00	0.00	*35.00F	✓

F=Franchise part.

Total Parts (S\$)

3,498.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS**Estimates on Miscellaneous Items**

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 PC FRT NUMBER PLATE	CPS 35.00
2	1	1 PC REAR NUMBER PLATE	As per spec 35.00
3	1	1 PC REVERSE CAMERA	As per spec 320.00
4	1	1 SET REVERSE SENSOR	As per spec 200.00
Sub Total (S\$)			590.00

No Qty Particulars

Amount

Estimates on Labour

No Particulars

Labour Items

Lab.Type

Amount

1	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR END PANEL, KNOCK & REPAIR REAR FENDER, REAR SPARE COMPARTMENT, REAR BOTH CHASSIS, TAILLAMP PANELS & REALIGN THE SAME	New	900.00 1,300.00
2	PUTTY & RESPRAY REAR BOOT, HINGES, REAR PANEL, TAILLAMP PANELS, REAR BUMPER, BOTH FENDERS, REAR SPARE TYRE COMPARTMENT & REAR AFFECTED AREAS	New	1,200.00 1100
3	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, GRILLE, RADIATOR & MOTOR, TO STRAIGHTEN, KNOCK & REPAIR FRT SUPPORT PANEL & REALIGN THE SAME	New	600.00 400
4	PUTTY & RESPRAY FRT BUMPER, SUPPORT PANEL, BONNET, FRT FENDERS	New	800.00 500
5	REMOVE & REFIX AIR-CON, CHECK, VACUUM & REFILL GAS	New	100.00 7
6	RUSTPROOFING	New	80.00 80

Gross Labour Cost (S\$) 4,080.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >