

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006617/ATCE2

Date: 29/09/2021

REFERENCE

Insured/Claimant: LEE SIEW POH PAUL Policy No: 2100463477-05
Date of Loss: 06/06/2021 Nature of Claim: OD Claim No: 5954829181SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGP8393X**
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD226126
Reg. Date: 29/04/2016 (Man. Year: 2015) Chassis No: WAUZZZ8U7GR066119
Colour: Blue Odometer: 55067 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$82,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R17 Rear Tyre Size: 235/55 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,391.00	4,885.60	2,505.40	33.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	1,842.00	2,910.00	61.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,143.00	6,727.60	5,415.40	44.60
+ GST 7.00/7.00% (S\$)	850.01	470.93	379.08	44.60
Nett Amount (S\$)	12,993.01	7,198.53	5,794.48	44.60

INSPECTION

Date of Assignment: 11/06/2021
Date Inspected: 10/06/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,125.00 FS	*1,700.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	109.00 FS	*- FS
3	1		*FRONT BUMPER AIR GRILLE - LH	Not Necessary	153.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Necessary	217.00 FS	*173.20 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	176.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Deformed	581.00 FS	*464.40 FS
7	1		*FRONT BUMPER UNDERRUN BAR	Cut	978.00 FS	*782.40 FS
8	1		*FRONT RADIATOR GRILLE	Cut	1,152.00 FS	*921.60 FS
9	1		*FRONT RADIATOR GRILLE STRIKER PLATE	Not Necessary	131.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT COVER	Not Necessary	65.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	123.00 FS	*- FS
12	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
13	1		*FRONT WHEEL SPOILER - LH	Not Necessary	73.00 FS	*- FS
14	2		*FRONT WHEEL ARCH TRIM - LH / RH	Necessary	1,056.00 FS	*844.00 FS
15	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	26.00 FS	*- FS
16	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS
17	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
18	1		*FRONT BUMPER REINFORCEMENT FORM	Not Necessary	102.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 7,391.00 4,885.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,000.00	1,150.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$)	4,752.00
				1,842.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >