



Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%20	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: China Taiping

Vehicle No : SMS 4843 D

Make & Model : HYUNDAI AVANTE

DATE: 7/6/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BOOT LID <i>Distorted</i>	1	\$ 1,895.00	\$ 1,895.00
2	BOOT LID BADGE WITH SWITCH <i>2nd</i>	1	\$ 356.00	\$ 356.00
3	BOOT LID EMBLEM (AVANTE) <i>3rd</i>	1	\$ 98.70	\$ 98.70
4	BOOT LID EMBLEM (S)	1	\$ 56.00	\$ 56.00
5	BOOT LID SROILER <i>crushed</i>	1	\$ 896.00	\$ 896.00
6	BOOT LID REVERSE CAMERA <i>2nd</i>	1	\$ 926.10	\$ 926.10
7	BOOT LID LAMP <i>ct</i>	2	\$ 694.20	\$ 1,388.40
8	BOOT LID STOPPER <i>new</i>	2	\$ 30.00	\$ 60.00
9	BOOT LID INNER LOCK <i>2nd</i>	1	\$ 296.20	\$ 296.20
10	BOOT LID LOCK CATCH <i>new</i>	1	\$ 43.70	\$ 43.70
11	BOOT LID WEATHERSTRIP <i>ct</i>	1	\$ 254.00	\$ 254.00
12	BOOT LID INNER TRIM <i>Delivered</i>	1	\$ 348.20	\$ 348.20
13	BOOT LID HINGE <i>Bent</i>	2	\$ 114.20	\$ 228.40
14	SMART ENTRY ANTENNA <i>crushed</i>	1	\$ 320.00	\$ 320.00
15	REAR BUMPER <i>Distorted</i>	1	\$ 654.00	\$ 654.00
16	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 97.70	\$ 195.40
17	REAR BUMPER BRACKET <i>2nd</i>	5	\$ 40.00	\$ 200.00
18	REAR BUMPER REFLECTOR <i>crushed</i>	2	\$ 689.00	\$ 1,378.00
19	REAR BUMPER REINFORCEMENT <i>Delivered</i>	1	\$ 394.80	\$ 394.80
20	REAR BUMPER REINFORCEMENT BRACKET <i>Bent</i>	2	\$ 197.10	\$ 394.20
21	REAR BUMPER UNDER COVER COVER <i>Delivered</i>	1	\$ 158.60	\$ 158.60
22	REAR BUMPER LOWER DIFFUSER <i>Delivered</i>	1	\$ 453.10	\$ 453.10
23	TAILLAMP <i>crushed</i>	2	\$ 1,052.10	\$ 2,104.20
24	TAILLAMP SIDE GARNISH <i>Missing</i>	2	\$ 68.00	\$ 136.00
25	TAILLAMP PANEL <i>crushed</i>	2	\$ 489.00	\$ 978.00
26	REAR WINDSCREEN <i>new</i>	1	\$ 845.00	\$ 845.00

1782

485

582

1328

+

+

+

+

+

186

+

90

402

+

+

+

+

386

+

[illegible]

