

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-57 AUTOBAY @ KAKI BUKIT, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

10/06/2021

OUR REF NO. SMJ 2977L

LIM RACHEL
BLK 102A BIDADARI PARK DRIVE,
#09-173,
SINGAPORE 341102

TPAxA.
Xiao Chen.

MMBSTA13AFH01985

ESTIMATE BILL FOR VEHICLE NO. SMJ 2977L MODEL : MITSUBISHI ATTRAGE 1.2CVT

LIST ITEM

1) BONNET	new		\$ 674.00	+
2) FRONT GRILLE	changed		\$ 549.00	✓
3) FRONT LOGO	new		\$ 59.00	✓
4) FRONT BUMPER	changed		\$ 873.00	✓ 699
5) FRONT BUMPER CLIPS	new	10PCS @\$8.90	\$ 89.00	20
6) FRONT BUMPER SIDE RETAINER	new	2PCS @\$64.00	\$ 128.00	+
7) FRONT BUMPER LOWER GRILLE	changed		\$ 297.00	156
8) FRONT BUMPER TOWING COVER	new		\$ 36.00	+
9) FOGLAMP GARNISH	new	2PCS @\$197.00	\$ 394.00	+
10) FOGLAMP	new	2PCS @\$499.00	\$ 998.00	+
11) FRONT BUMPER REINFORCEMENT	Changed		\$ 462.00	350
12) FRONT BUMPER TOP BRACKET	changed		\$ 69.00	✓
13) SUPPORT PANEL	new		\$ 801.00	+
14) HEADLAMP	2H changed	2PCS @\$870.60	\$ 1,741.20	663
15) AIR-CON CONDENSOR	new		\$ 671.00	+
16) RADIATOR ASSEMBLY	new		\$ 597.00	+
			\$ 8,438.20	
LESS DISCOUNT - 10%			\$ 843.82	
			\$ 7,594.38	

SPECIAL NETT ITEM

1) FRONT LICENCE PLATE WITH HOLDER	changed	\$ 55.00	✓
		\$ 55.00	

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	\$ 120.00	30
2) TO APPLY UNDERSEALING ON AFFECTED AREAS	\$ 120.00	x
3) TO REMOVE/REFIX HEADLAMP ASSY, REALIGNMENT LIGHTING SYSTEM	\$ 120.00	30
4) TO REMOVE/REFIX AIR-CON CONDENSOR, PIPING SYSTEM & TOP UP GAS	\$ 180.00	x
5) TO REMOVE/REFIX RADIATOR ASSY & CONDUCT PRESSURE TEST	\$ 180.00	x
6) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC	\$ 880.00	300
7) TO RESPRAY ON THE AFFECTED AREAS	\$ 880.00	200
		\$ 2,480.00
		\$ 10,129.38
GRAND TOTAL		

560

Adrian Cj

L/S 11/06/21.

03 Days

total: 2932.50.

L/S: 2.3K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: