



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 068811
ATTN: STACEY NG

Ref: CS3/ASM21006628/Gtce2
Date: 24/08/2021
Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FY 2739L	Veh. Inspected	FJ 823T
Policy No.		Coverage (\$)	0.00
Claim No.	S1M03B16	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	11/06/2021


2. Vehicle Particulars & Condition

Make & Model	YAMAHA RXZ	c.c	133
Engine No.	HIDDEN	Year of Reg.	1990
Chassis No.	2UX004704	Colour	RED
Odometer	48233 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80-17	IRC	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80-17	MICHELIN	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.	
--	---

5. General Information

Accident Date	29/05/2021	Inspect Date / Time	01/07/2021 (01:00 PM)
Survey held at	GLEN ENTERPRISE PTE LTD 1100/1102 SERANGOON ROAD SINGAPORE 328196		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------

Report Ref No. CS3/ASM21006628/Gtce2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.