Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jenny Lew Date: 17 Jun 2021

Preliminary Advice

Insured Vehicle No : SLZ7785T

TP Vehicle No : SMQ1265C Accident Date : 07/06/2021 Make : TOYOTA VIOS Assignment Date : 11/06/2021

Date of Inspection : 11/06/2021 Est. Duration of Repair : 35

Inspection At : OPTIMA WERKZ PTE LTD (HQ)

10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05 AMK AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 66,769.00 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 46,258.00 |
| Check Items (Estimated) | :S\$ | 12,973.75 |
| Total | :S\$ | 59,231.75 |

Lump Sum Repair :S\$

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|---|---|
|) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
|) | Other comments : |