

ASS. REC. BY:

REF:

C72/21008629/kg

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMQ 1265C

at Workshop m/s Optima

of _____

Insured: SLZ 7785T

Policy No. DMHCSNW00008042000

Claims No. SNM21D203215/C09


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 875k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 35 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SMQ 1265C

Yr Regn:

10, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

c.c.

1996

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR 2B 231F 3201189856

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STDA/Rlm or

Tyre Size: F:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

7/6/21

D.O.I.

11/6/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision. ✓

Date / Time

Action / Instruction

1. Berkey Hat, got BZ

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

S + RS. \$ _____

Fees _____

Others _____

TOTAL

Report Format:

Lump Sum / I.B.I. (\$ _____)

Date: 10.06.2021

Vehicle No: SMQ1265C

Model: TOYOTA VIOS 1.5E

Chassis: MR2B23F3201189856-2019

Reg.Year: 2019

Third Party Insurer:

CHINA TAIPING

Third Party Veh No:

SLZ7785T

Date of Accident:

07.06.2021

Estimator:

TING AN

Surveyor:

Not Authorized

21 Days

Returning After Pain

35 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		<i>Ry</i> \$772.00
2	REAR BOOTLID HINGE LH	1		<i>Di</i> \$85.00
3	REAR BOOTLID HINGE RH	1		<i>Di</i> \$85.00
4	REAR BOOTLID "VIOS" EMBLEM	1		<i>Ry</i> \$75.00
5	REAR BOOTLID "E" EMBLEM	1		<i>Ry</i> \$55.00
6	REAR BOOTLID "TOYOTA" EMBLEM	1		<i>Ry</i> \$75.00
7	REAR BOOTLID WEATHERSTIPE	1		<i>Ref</i> \$175.00
8	REAR BOOTLID INNER LOCK	1		<i>Tr</i> \$399.00
9	REAR BOOTLID STRIKER	1		<i>Ry</i> \$28.00
10	REAR BOOTLID LAMP LH	1		\$253.00
11	REAR BOOTLID LAMP RH	1		\$253.00
12	REAR BOOTLID INSULATOR	1		<i>Ref</i> \$325.00
13	REAR TAIL LAMP LH	1		<i>Ry</i> \$360.00
14	REAR TAIL LAMP RH	1		\$360.00
15	REAR TAIL LAMP BRACKET LH	1		<i>CM</i> \$65.00
16	REAR TAIL LAMP BRACKET RH	1		<i>Tr</i> \$65.00
17	REAR BUMPER	1		<i>Ry</i> \$505.00
18	REAR BUMPER SIDE BRACKET LH	1		<i>Ry</i> \$154.00
19	REAR BUMPER SIDE BRACKET RH	1		<i>Di</i> \$154.00
20	REAR BUMPER REINFORCEMENT	1		<i>Ry</i> \$322.00
21	REAR BUMPER ANTENNA SENSOR	1		<i>Tr</i> \$82.00
22	REAR BUMPER FOG LAMP LH	1		<i>Ry</i> \$94.00
23	REAR BUMPER FOG LAMP RH	1		<i>Tr</i> \$94.00
24	REAR END PANEL	1		<i>Ry</i> \$742.00
25	REAR END PANEL UPPER COVERING	1		<i>Di</i> \$278.00
26	REAR FLOOR PANEL	1		<i>Ref</i> \$678.00
27	REAR SPARE TYRE UPPER BOARD	1		\$385.00
28	REAR BOOT FLOOR TRIM LH	1		\$350.00
29	REAR BOOT FLOOR TRIM RH	1		\$350.00
30	REAR DOOR LH	1		<i>Ry</i> \$934.00
31	REAR FENDER LH	1		<i>Ry</i> \$907.00
32	REAR AIR DUCT LH	1		<i>Di</i> \$56.00
33	REAR MUD FLAP LH	1		<i>Di</i> \$65.00
34	REAR MUD FLAP RH	1		<i>Di</i> \$65.00
35	REAR SIDE FLOOR PANEL LH	1		<i>Ry</i> \$140.00
36	REAR SIDE FLOOR PANEL RH	1		\$140.00

Head office

8 Kung Chong Road Singapore 156143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10.06.2021
Vehicle No: SMQ1265C
Model: TOYOTA VIOS 1.5E
Chassis: MR2B23F3201189856-2019
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLZ7785T
Date of Accident: 07.06.2021
Estimator: TING AN
Surveyor:

37	REAR FLOOR PANEL SIDE RAIL LH	1	B ₁	\$320.00	✓
38	REAR FLOOR PANEL SIDE RAIL RH	1	R	\$320.00	X
39	REAR WINDSCREEN MOULDING	1	Acc	\$95.00	?
40	REAR ABSORBER LH	1	B ₁	\$129.00	✓
41	REAR ABSORBER RH	1	I ₂	\$129.00	X
42	REAR WHEEL BEARING LH	1		\$649.00	?
43	REAR WHEEL BEARING RH	1	I ₂	\$649.00	X
44	REAR AXLE BEAM	1		\$3,746.00	?
45	FRONT BONNET	1	B ₁	\$924.00	✓
46	FRONT BONNET INSULATOR	1	Return	\$280.00	✓
47	FRONT BONNET HINGE LH	1	B ₁	\$65.00	✓
48	FRONT BONNET HINGE RH	1	B ₁	\$65.00	✓
49	FRONT BONNET STAY PANEL	1	B ₁	\$149.00	✓
50	FRONT BONNET LOCK	1	B ₁	\$135.00	✓
51	FRONT BONNET STAND	1	D ₁	\$65.00	✓
52	FRONT WIPER AIR GRILLE	1	CMA	\$645.00	✓
53	FRONT WIPER AIR GRILLE GARNISH COVER LH	1	D ₁	\$65.00	✓
54	FRONT WIPER AIR GRILLE GARNISH COVER RH	1	I ₂	\$65.00	X
55	FRONT HEADLAMP LH	1	CMA	\$1,144.00	✓
56	FRONT HEADLAMP RH	1	CMA	\$1,144.00	✓
57	FRONT HEADLAMP UPPER PANEL LH	1	B ₁	\$109.00	✓
58	FRONT HEADLAMP UPPER PANEL RH	1	B ₁	\$109.00	✓
59	FRONT BUMPER	1	Z ₁	\$486.00	✓
60	FRONT BUMPER SIDE BRACKET LH	1	CMA	\$90.00	✓
61	FRONT BUMPER SIDE BRACKET RH	1	CM	\$90.00	✓
62	FRONT BUMPER REINFORCEMENT	1	B ₁	\$399.00	✓
63	FRONT BUMPER REINFORCEMENT SUPPORT BRACKET LH	1	B ₁	\$103.00	✓
64	FRONT BUMPER REINFORCEMENT SUPPORT BRACKET RH	1	B ₁	\$103.00	✓
65	FRONT BUMPER LOWER GRILLE	1	CMA	\$269.00	✓
66	FRONT BUMPER FOG LAMP LH	1	M ₁	\$325.00	✓
67	FRONT BUMPER FOG LAMP RH	1	I ₂	\$325.00	X
68	FRONT BUMPER FOG LAMP GARNISH COVER LH	1	M ₁	\$93.00	✓
69	FRONT BUMPER FOG LAMP GARNISH COVER RH	1	I ₂	\$93.00	X
70	FRONT BUMPER TOWING COVER	1	M ₁	\$62.00	✓
71	FRONT BUMPER UNDER COVER CENTER	1	CM	\$328.00	✓
72	FRONT BUMPER UNDER COVER LH	1		\$215.00	?
73	FRONT BUMPER UNDER COVER RH	1		\$145.00	?
74	FRONT BUMPER UPPER COVER	1	M ₁ I ₂	\$273.00	✓
75	FRONT AIR DUCT LH	1	CM	\$90.00	✓

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1312 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10.06.2021
Vehicle No: SMQ1265C
Model: TOYOTA VIOS 1.5E
Chassis: MR2B23F3201189856-2019
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLZ7785T
Date of Accident: 07.06.2021
Estimator: TING AN
Surveyor:

76	FRONT AIR DUCT RH	1		\$90.00	?
77	FRONT GRILLE	1	CM	\$240.00	✓
78	FRONT GRILLE TRIM LH	1	hiy	\$68.00	✓
79	FRONT GRILLE TRIM RH	1	hiy	\$68.00	✓
80	FRONT GRILLE GARNISH COVER	1	hiy	\$85.00	✓
81	FRONT GRILLE EMBLEM	1	hiy	\$58.00	✓
82	FRONT A-PILLAR GARNISH COVER LH	1	hiy	\$45.00	✓
83	FRONT A-PILLAR GARNISH COVER RH	1	hiy	\$45.00	x
84	FRONT FENDER LH	1	Bu	\$765.00	✓
85	FRONT FENDER RH	1	Bu	\$765.00	✓
86	FRONT FENDER INNER LINER LH	1	CM	\$220.00	✓
87	FRONT FENDER INNER LINER RH	1		\$220.00	?
88	FRONT DOOR LH	1	R	\$1,091.00	x
89	FRONT DOOR RH	1	R	\$1,091.00	x
90	FRONT WINDSCREEN GLASS	1	CM	\$1,319.00	✓
91	FRONT SUPPORT PANEL	1	R	\$978.00	✓
92	FRONT WASHER TANK	1	Ne	\$210.00	✓
93	FRONT WASHER TANK MOTOR	1		\$529.00	?
94	FRONT AIR FILTER ASSY	1	CM	\$1,077.00	✓
95	FRONT HORN	1	Ne	\$143.00	✓
96	FRONT FUSE BOX ASSY	1		\$484.00	?
97	FRONT INTAKE MANIFOLD	1		\$836.00	?
98	FRONT AIR INTAKE HOSE	1		\$79.00	?
99	FRONT ALTERNATOR	1		\$2,805.00	?
100	FRONT ENGINE MOUNTING LH	1		\$411.00	?
101	FRONT ENGINE MOUNTING RH	1	CM	\$411.00	✓
102	FRONT TIMING COVER	1	CM	\$746.00	✓
103	FRONT BATTERY SUPPORT	1		\$134.00	?
104	FRONT RADIATOR	1	R	\$2,052.00	✓
105	FRONT RADIATOR BRACKET LH	1	hiy	\$75.00	✓
106	FRONT RADIATOR BRACKET RH	1	hiy	\$75.00	✓
107	FRONT RADIATOR FAN SHROULD	1		\$264.00	?
108	FRONT RADIATOR FAN BLADE	1		\$202.00	?
109	FRONT RADIATOR FAN MOTOR	1		\$471.00	?
110	FRONT RADIATOR TOP HOSE	1		\$52.00	?
111	FRONT RADIATOR BOTTOM HOSE	1		\$45.00	?
112	FRONT AIRCON CONDENSER	1	R	\$1,133.00	✓
113	FRONT AIRCON CONDENSER PRESSURE PIPE	1	Ne	\$289.00	✓
114	FRONT AIRCON CONDENSER LIQUID TUBE	1		\$506.00	?

Head office

6 Kung Chong Road Singapore 169143
Tel (+65) 6472 1313 | Fax (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel (+65) 6484 9019 | Fax (+65) 6481 1003

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel (+65) 6481 1522 | Fax (+65) 6481 1011



Date: 10.06.2021
Vehicle No: SMQ1265C
Model: TOYOTA VIOS 1.5E
Chassis: MR2B23F3201189856-2019
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLZ7785T
Date of Accident: 07.06.2021
Estimator: TING AN
Surveyor:

115	FRONT DASHBOARD AIRBAG	1	Bury	\$3,883.00	✓
116	FRONT STEERING WHEEL AIRBAG	1	h	\$3,727.00	✓
117	FRONT DASHBOARD LOWER AIRBAG RH	1	h	\$2,479.00	✓
118	FRONT DASHBOARD	1	Th	\$884.00	✓
119	FRONT GLOVEBOX COMPARTMENT	1	h	\$985.00	✓
120	FRONT CONSOLE BOX TRIM LH	1	h	\$476.00	✓
121	ROOF TOP SIDE AIRBAG LH	1	Bury	\$1,930.00	✓
122	ROOF TOP SIDE AIRBAG RH	1	h	\$1,930.00	✓
123	FRONT SAFETY BELT LH	1	Th	\$995.00	✓
124	FRONT SAFETY BELT RH	1		\$995.00	✓
125	REAR SAFETY BELT LH	1	Th	\$916.00	✓
126	REAR SAFETY BELT RH	1		\$916.00	✓
127	AIRBAG CONTROL UNIT	1	h	\$1,203.00	✓
128	FRONT AIRBAG IMPACT SENSOR LH	1	h	\$374.00	✓
129	FRONT AIRBAG IMPACT SENSOR RH	1	h	\$374.00	✓
130	REAR AIRBAG IMPACT SENSOR LH	1	h	\$898.00	✓
131	REAR AIRBAG IMPACT SENSOR RH	1	h	\$898.00	✓
132	ROOF TOP SIDE AIRBAG IMPACT SENSOR LH	1	h	\$691.00	✓
133	ROOF TOP SIDE AIRBAG IMPACT SENSOR RH	1	h	\$691.00	✓
134	ROOF TOP LINING	1	Th	\$2,375.00	✓
135	REAR FENDER RH	1		REPAIR	✓
SUB TOTAL				\$72,212.00	
LESS 25%				-\$18,053.00	
PARTS TOTAL				\$54,159.00	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BUMPER CLIPS	1		h \$50.00	✓
2	REAR BUMPER REVERSE SENSOR	1		Th \$300.00	200Sn
3	REAR NUMBER PLATE	1		h \$40.00	✓
4	REAR NUMBER PLATE HOLDER	1		\$40.00	45Sn
5	REAR END PANEL UPPER COVERING CLIPS	1		h \$30.00	✓
6	REAR BOOTLID INSULATOR CLIPS	1		h \$30.00	✓
7	REAR WINDSCREEN SEALANT	1		h \$80.00	40Sn
8	FRONT BONNET INSULATOR CLIPS	1		h \$40.00	✓
9	FRONT BUMPER CLIPS	1		h \$50.00	✓
10	FRONT NUMBER PLATE	1		h \$40.00	45Sn
11	FRONT NUMBER PLATE HOLDER	1		\$40.00	

Head office

6 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9010 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10.06.2021
Vehicle No: SMQ1265C
Model: TOYOTA VIOS 1.5E
Chassis: MR2B23F3201189856-2019
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLZ7785T
Date of Accident: 07.06.2021
Estimator: TING AN
Surveyor:

12	FRONT BUMPER UPPER COVER CLIPS	1	na	\$30.00	✓
13	FRONT FENDER INNER LINER CLIPS LH	1	na	\$30.00	✓
14	FRONT FENDER INNER LINER CLIPS RH	1	na	\$30.00	X
15	FRONT WINDSCREEN SEALANT	1	na	\$80.00	4000
16	FRONT RADIATOR COOLANT	1	na	\$60.00	✓
17	FRONT BATTERY	1		\$250.00	?
18	ROOF TOP LINING CLIPS	1	na	\$80.00	✓
S/N TOTAL				\$1,300.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$3,000.00

2200

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$2,500.00

1000

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL, REAR FENDER LH, REAR FENDER RH, REAR DOOR LH, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

\$2,800.00

2600

LABOUR CHARGES REMOVE & REFIX REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT, REAR INNER TRIM, ROOF LINING & ETC. TO EFFECT REPLACE REAR FENDER LH.

\$300.00

260

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00

50

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC.

\$150.00

120

LABOUR CHARGES TO REMOVE, REPLACE, REIFX FRONT DASHBOARD & ETC.

\$300.00

250

LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, REAR SAFETY BELT LH & RH, STEERING WHEEL AIRBAG, FRONT DASHBOARD AIRBAG, FRONT DASHBOARD LOWER AIRBAG RH, ROOF TOP SIDE AIRBAG LH & RH.

\$500.00

400

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER LH & RH, REAR WHEEL BEARING

\$350.00

200

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 0019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011



Date: 10.06.2021
Vehicle No: SMQ1265C
Model: TOYOTA VIOS 1.5E
Chassis: MR2B23F3201189856-2019
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLZ7785T
Date of Accident: 07.06.2021
Estimator: TING AN
Surveyor:

LH & RH, REAR AXLE BEAM & ETC.

TO DIAGNOSE & RESET AIRBAG CONTROL UNIT.

\$300.00 } 2501

TO DIAGNOS FAULT CODE & RESET MEMORY.

\$150.00 }

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$500.00 2401

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 2

TO REFILL AIRCON GAS.

\$80.00 ✓

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$200.00 601

LABOUR TOTAL \$11,310.00

TING AN

TOTAL

\$66,769.00

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9010 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	381N
Vehicle Details	
Vehicle No.:	SMQ1265C
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2021
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	2NR5395149
Chassis No.:	MR2B23F3201189856
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,787.00
Original Registration Date:	30 Oct 2019
First Registration Date:	30 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$13,787.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2029
PARF Rebate Amount:	\$10,340.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,309.00
COE Rebate Amount:	\$27,115.00
Total Rebate Amount:	\$37,455.00

The information contained herein is correct as at 07 Jun 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/06/2021 11:25 (SGT)
Date of Accident	07/06/2021 07:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	KJE EXPRESSWAY (BEFORE EXIT 3)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMQ1265C
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CRAFT LEASING PTE LTD
Company Reg No	2XXXXX381N
Email Address	ADMIN@CRAFTLEASING.COM
Mobile Phone No	(Phone) +65-93838162
Alternative Phone No	+65-93838162

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496


INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5109925523-01
Cover Note Number	-

DRIVER

Name of Driver	SIM SEE HOCK
NRIC No	SXXXX046Z

SKETCH PLAN



- (A) - SMQ1265C
- (B) - 427786T
- (C) - 425274B
- (D) - SKT2842
- (E) - SHC6467L
- (F) - 4F6484E
- (G) - SK3338K
- (H) - SD8302L
- (I) - SKP5661Y


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT: T/2421607/2020.

→ vehicle claim repair under Optima West PHEVA.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

8/6/2021

Kee 8/6/21