

ASS. REC. BY:

REF:

C72/21006629/kgf3

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 12656

Yr Regn:

10.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios

C.C.

1496

Colour

N. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR 2B 23F 3201189856

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

7/6/21

D.O.I.

11/6/2021

Survey held at

Des. of Damages:

Frt / Rear /

O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Bertan Plat, 801 BZ

2117 L1 Rm 837, 500k Confirm Used to 29269, 44107

Date/Time, File Pass to?

☐

: Prel. Report

1) 23/7 typist

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

35

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

NER-7P

Lump Sum / I.B.I. (\$) :

37500

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Date: 10.06.2021

Vehicle No: SMQ1265C

Model: TOYOTA VIOS 1.5E

Chassis: MR2B23F3201189856-2019

Reg.Year: 2019

Third Party Insurer:

Third Party Veh No:

Date of Accident:

Estimator:

Surveyor:

CHINA TAIPING

SLZ7785T

07.06.2021

TING AN

Not Authorised

L1 Lump \$37,500

Return After Pairs

35 days

## ESTIMATE

| NO. | DESCRIPTION                        | QTY | UNIT S\$ | AMOUNT S\$     |
|-----|------------------------------------|-----|----------|----------------|
| 1   | REAR BOOTLID                       | 1   |          | Ry \$772.00    |
| 2   | REAR BOOTLID HINGE LH              | 1   |          | Diy \$85.00    |
| 3   | REAR BOOTLID HINGE RH              | 1   |          | Diy \$85.00    |
| 4   | REAR BOOTLID "VIOS" EMBLEM         | 1   |          | Ry \$75.00     |
| 5   | REAR BOOTLID "E" EMBLEM            | 1   |          | Ry \$55.00     |
| 6   | REAR BOOTLID "TOYOTA" EMBLEM       | 1   |          | Ry \$75.00     |
| 7   | REAR BOOTLID WEATHERSTIPE          | 1   |          | Refum \$175.00 |
| 8   | REAR BOOTLID INNER LOCK            | 1   |          | Tm \$399.00    |
| 9   | REAR BOOTLID STRIKER               | 1   |          | Ry \$28.00     |
| 10  | REAR BOOTLID LAMP LH               | 1   |          | Ry \$253.00    |
| 11  | REAR BOOTLID LAMP RH               | 1   |          | Ry \$253.00    |
| 12  | REAR BOOTLID INSULATOR 228.40      | 1   |          | Refum \$325.00 |
| 13  | REAR TAIL LAMP LH                  | 1   |          | Ry \$360.00    |
| 14  | REAR TAIL LAMP RH                  | 1   |          | Ry \$360.00    |
| 15  | REAR TAIL LAMP BRACKET LH          | 1   |          | Ry \$65.00     |
| 16  | REAR TAIL LAMP BRACKET RH          | 1   |          | Ry \$65.00     |
| 17  | REAR BUMPER 482.20                 | 1   |          | Ry \$505.00    |
| 18  | REAR BUMPER SIDE BRACKET LH        | 1   |          | Ry \$154.00    |
| 19  | REAR BUMPER SIDE BRACKET RH        | 1   |          | Diy \$154.00   |
| 20  | REAR BUMPER REINFORCEMENT 298      | 1   |          | Ry \$322.00    |
| 21  | REAR BUMPER ANTENNA SENSOR         | 1   |          | Ry \$82.00     |
| 22  | REAR BUMPER FOG LAMP LH            | 1   |          | Ry \$94.00     |
| 23  | REAR BUMPER FOG LAMP RH            | 1   |          | Ry \$94.00     |
| 24  | REAR END PANEL 691                 | 1   |          | Ry \$742.00    |
| 25  | REAR END PANEL UPPER COVERING      | 1   |          | Diy \$278.00   |
| 26  | REAR FLOOR PANEL                   | 1   |          | Ry \$678.00    |
| 27  | REAR SPARE TYRE UPPER BOARD 226.70 | 1   |          | Ry \$385.00    |
| 28  | REAR BOOT FLOOR TRIM LH 185        | 1   |          | Refum \$350.00 |
| 29  | REAR BOOT FLOOR TRIM RH 185        | 1   |          | Ry \$350.00    |
| 30  | REAR DOOR LH                       | 1   |          | Ry \$934.00    |
| 31  | REAR FENDER LH 904.55              | 1   |          | Ry \$907.00    |
| 32  | REAR AIR DUCT LH                   | 1   |          | Diy \$56.00    |
| 33  | REAR MUD FLAP LH                   | 1   |          | Ry \$65.00     |
| 34  | REAR MUD FLAP RH                   | 1   |          | Diy \$65.00    |
| 35  | REAR SIDE FLOOR PANEL LH           | 1   |          | Ry \$140.00    |
| 36  | REAR SIDE FLOOR PANEL RH           | 1   |          | Ry \$140.00    |

### Head office

8 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10.06.2021  
Vehicle No: SMQ1265C  
Model: TOYOTA VIOS 1.5E  
Chassis: MR2B23F3201189856-2019  
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SLZ7785T  
Date of Accident: 07.06.2021  
Estimator: TING AN  
Surveyor:

|    |                                               |   |         |        |            |   |
|----|-----------------------------------------------|---|---------|--------|------------|---|
| 37 | REAR FLOOR PANEL SIDE RAIL LH                 | 1 |         | Ry     | \$320.00   | ✓ |
| 38 | REAR FLOOR PANEL SIDE RAIL RH                 | 1 |         | R      | \$320.00   | x |
| 39 | REAR WINDSCREEN MOULDING                      | 1 |         | N/A    | \$95.00    | x |
| 40 | REAR ABSORBER LH                              | 1 |         | Ry     | \$129.00   | ✓ |
| 41 | REAR ABSORBER RH                              | 1 |         | Ln     | \$129.00   | x |
| 42 | REAR WHEEL BEARING LH                         | 1 |         | Ry     | \$649.00   | 2 |
| 43 | REAR WHEEL BEARING RH                         | 1 |         | Ln     | \$649.00   | x |
| 44 | REAR AXLE BEAM                                | 1 | 1912.80 | Ry     | \$3,746.00 | 3 |
| 45 | FRONT BONNET                                  | 1 |         | Ry     | \$924.00   | ✓ |
| 46 | FRONT BONNET INSULATOR                        | 1 |         | Return | \$280.00   | ✓ |
| 47 | FRONT BONNET HINGE LH                         | 1 |         | Ry     | \$65.00    | ✓ |
| 48 | FRONT BONNET HINGE RH                         | 1 |         | Ry     | \$65.00    | ✓ |
| 49 | FRONT BONNET STAY PANEL                       | 1 |         | Ry     | \$149.00   | ✓ |
| 50 | FRONT BONNET LOCK                             | 1 |         | Ry     | \$135.00   | ✓ |
| 51 | FRONT BONNET STAND                            | 1 |         | D/I    | \$65.00    | ✓ |
| 52 | FRONT WIPER AIR GRILLE                        | 1 |         | CRA    | \$645.00   | ✓ |
| 53 | FRONT WIPER AIR GRILLE GARNISH COVER LH       | 1 |         | D/I    | \$65.00    | ✓ |
| 54 | FRONT WIPER AIR GRILLE GARNISH COVER RH       | 1 |         | Ln     | \$65.00    | x |
| 55 | FRONT HEADLAMP LH                             | 1 |         | CRA    | \$1,144.00 | ✓ |
| 56 | FRONT HEADLAMP RH                             | 1 |         | CRA    | \$1,144.00 | ✓ |
| 57 | FRONT HEADLAMP UPPER PANEL LH                 | 1 |         | Ry     | \$109.00   | ✓ |
| 58 | FRONT HEADLAMP UPPER PANEL RH                 | 1 |         | Ry     | \$109.00   | ✓ |
| 59 | FRONT BUMPER                                  | 1 | 481.10  | Ln     | \$486.00   | ✓ |
| 60 | FRONT BUMPER SIDE BRACKET LH                  | 1 |         | CRA    | \$90.00    | ✓ |
| 61 | FRONT BUMPER SIDE BRACKET RH                  | 1 |         | CRA    | \$90.00    | ✓ |
| 62 | FRONT BUMPER REINFORCEMENT                    | 1 |         | Ry     | \$399.00   | ✓ |
| 63 | FRONT BUMPER REINFORCEMENT SUPPORT BRACKET LH | 1 |         | Ry     | \$103.00   | ✓ |
| 64 | FRONT BUMPER REINFORCEMENT SUPPORT BRACKET RH | 1 |         | Ry     | \$103.00   | ✓ |
| 65 | FRONT BUMPER LOWER GRILLE                     | 1 |         | CRA    | \$269.00   | ✓ |
| 66 | FRONT BUMPER FOG LAMP LH                      | 1 |         | M/I    | \$325.00   | ✓ |
| 67 | FRONT BUMPER FOG LAMP RH                      | 1 |         | Ln     | \$325.00   | x |
| 68 | FRONT BUMPER FOG LAMP GARNISH COVER LH        | 1 |         | M/I    | \$93.00    | ✓ |
| 69 | FRONT BUMPER FOG LAMP GARNISH COVER RH        | 1 |         | Ln     | \$93.00    | x |
| 70 | FRONT BUMPER TOWING COVER                     | 1 |         | M/I    | \$62.00    | ✓ |
| 71 | FRONT BUMPER UNDER COVER CENTER               | 1 |         | CRA    | \$328.00   | ✓ |
| 72 | FRONT BUMPER UNDER COVER LH                   | 1 |         | Ln     | \$215.00   | x |
| 73 | FRONT BUMPER UNDER COVER RH                   | 1 |         | Ln     | \$145.00   | x |
| 74 | FRONT BUMPER UPPER COVER                      | 1 |         | D/I    | \$273.00   | ✓ |
| 75 | FRONT AIR DUCT LH                             | 1 |         | CRA    | \$90.00    | ✓ |

Date: 10.06.2021  
Vehicle No: SMQ1265C  
Model: TOYOTA VIOS 1.5E  
Chassis: MR2B23F3201189856-2019  
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SLZ7785T  
Date of Accident: 07.06.2021  
Estimator: TING AN  
Surveyor:

|     |                                           |   |  |        |            |   |
|-----|-------------------------------------------|---|--|--------|------------|---|
| 76  | FRONT AIR DUCT RH                         | 1 |  | Det    | \$90.00    | 2 |
| 77  | FRONT GRILLE                              | 1 |  | CM     | \$240.00   | 1 |
| 78  | FRONT GRILLE TRIM LH                      | 1 |  | mi     | \$68.00    | 1 |
| 79  | FRONT GRILLE TRIM RH                      | 1 |  | mi     | \$68.00    | 1 |
| 80  | FRONT GRILLE GARNISH COVER                | 1 |  | mi     | \$85.00    | 1 |
| 81  | FRONT GRILLE EMBLEM                       | 1 |  | mi     | \$58.00    | 1 |
| 82  | FRONT A-PILLAR GARNISH COVER LH           | 1 |  | mi     | \$45.00    | 1 |
| 83  | FRONT A-PILLAR GARNISH COVER RH           | 1 |  | Sm     | \$45.00    | X |
| 84  | FRONT FENDER LH 685                       | 1 |  | Bu     | \$765.00   | 1 |
| 85  | FRONT FENDER RH 685                       | 1 |  | Bu     | \$765.00   | 1 |
| 86  | FRONT FENDER INNER LINER LH               | 1 |  | CM     | \$220.00   | 1 |
| 87  | FRONT FENDER INNER LINER RH               | 1 |  | R      | \$220.00   | X |
| 88  | FRONT DOOR LH                             | 1 |  | R      | \$1,091.00 | X |
| 89  | FRONT DOOR RH                             | 1 |  | R      | \$1,091.00 | X |
| 90  | FRONT WINDSCREEN GLASS                    | 1 |  | CM     | \$1,319.00 | 1 |
| 91  | FRONT SUPPORT PANEL 971.85                | 1 |  | Bu     | \$978.00   | 1 |
| 92  | FRONT WASHER TANK                         | 1 |  | Det    | \$210.00   | 1 |
| 93  | FRONT WASHER TANK MOTOR 456               | 1 |  | CM     | \$529.00   | 2 |
| 94  | FRONT AIR FILTER ASSY 935.90              | 1 |  | CM     | \$1,077.00 | 1 |
| 95  | FRONT HORN                                | 1 |  | Det    | \$143.00   | 1 |
| 96  | FRONT FUSE BOX ASSY                       | 1 |  | Det/Sm | \$484.00   | 2 |
| 97  | FRONT INTAKE MANIFOLD                     | 1 |  | CM     | \$836.00   | 2 |
| 98  | FRONT AIR INTAKE HOSE                     | 1 |  | Det    | \$79.00    | 2 |
| 99  | FRONT ALTERNATOR 2306.10                  | 1 |  | CM     | \$2,805.00 | 2 |
| 100 | FRONT ENGINE MOUNTING LH                  | 1 |  | Di     | \$411.00   | 2 |
| 101 | FRONT ENGINE MOUNTING RH                  | 1 |  | CM     | \$411.00   | 1 |
| 102 | FRONT TIMING COVER                        | 1 |  | CM     | \$746.00   | 1 |
| 103 | FRONT BATTERY SUPPORT                     | 1 |  | Di     | \$134.00   | 2 |
| 104 | FRONT RADIATOR 1740.50                    | 1 |  | Bu     | \$2,052.00 | 1 |
| 105 | FRONT RADIATOR BRACKET LH                 | 1 |  | Di     | \$75.00    | 1 |
| 106 | FRONT RADIATOR BRACKET RH                 | 1 |  | Di     | \$75.00    | 1 |
| 107 | FRONT RADIATOR FAN SHROULD                | 1 |  | CM     | \$264.00   | 2 |
| 108 | FRONT RADIATOR FAN BLADE                  | 1 |  | Sm     | \$202.00   | X |
| 109 | FRONT RADIATOR FAN MOTOR                  | 1 |  | Sm     | \$471.00   | X |
| 110 | FRONT RADIATOR TOP HOSE                   | 1 |  | Sm     | \$52.00    | X |
| 111 | FRONT RADIATOR BOTTOM HOSE                | 1 |  | Sm     | \$45.00    | 2 |
| 112 | FRONT AIRCON CONDENSER                    | 1 |  | Bu     | \$1,133.00 | 1 |
| 113 | FRONT AIRCON CONDENSER PRESSURE PIPE      | 1 |  | Det    | \$289.00   | 1 |
| 114 | FRONT AIRCON CONDENSER LIQUID TUBE 209.10 | 1 |  | Bu     | \$506.00   | 2 |

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10.06.2021  
 Vehicle No: SMQ1265C  
 Model: TOYOTA VIOS 1.5E  
 Chassis: MR2B23F3201189856-2019  
 Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: SLZ7785T  
 Date of Accident: 07.06.2021  
 Estimator: TING AN  
 Surveyor:

|             |                                       |         |   |         |              |   |
|-------------|---------------------------------------|---------|---|---------|--------------|---|
| 115         | FRONT DASHBOARD AIRBAG                | 2334-10 | 1 | Bury    | \$3,883.00   | ✓ |
| 116         | FRONT STEERING WHEEL AIRBAG           | 3206-80 | 1 | u       | \$3,727.00   | ✓ |
| 117         | FRONT DASHBOARD LOWER AIRBAG RH       | 1861-90 | 1 | u       | \$2,479.00   | ✓ |
| 118         | FRONT DASHBOARD                       |         | 1 | Tn      | \$884.00     | ✓ |
| 119         | FRONT GLOVEBOX COMPARTMENT            |         | 1 | Red Box | \$985.00     | ✓ |
| 120         | FRONT CONSOLE BOX TRIM LH             |         | 1 | Nil     | \$476.00     | ✓ |
| 121         | ROOF TOP SIDE AIRBAG LH               | 1898-20 | 1 | Bury    | \$1,930.00   | ✓ |
| 122         | ROOF TOP SIDE AIRBAG RH               | 1898-20 | 1 | u       | \$1,930.00   | ✓ |
| 123         | FRONT SAFETY BELT LH                  | 842-50  | 1 | Tn      | \$995.00     | ✓ |
| 124         | FRONT SAFETY BELT RH                  |         | 1 | u       | \$995.00     | ✓ |
| 125         | REAR SAFETY BELT LH                   | 781-40  | 1 | Tn      | \$916.00     | ✓ |
| 126         | REAR SAFETY BELT RH                   |         | 1 | u       | \$916.00     | ✓ |
| 127         | AIRBAG CONTROL UNIT                   |         | 1 | Nil     | \$1,203.00   | ✓ |
| 128         | FRONT AIRBAG IMPACT SENSOR LH         |         | 1 | Nil     | \$374.00     | ✓ |
| 129         | FRONT AIRBAG IMPACT SENSOR RH         |         | 1 | Nil     | \$374.00     | ✓ |
| 130         | REAR AIRBAG IMPACT SENSOR LH          |         | 1 | h       | \$898.00     | ✓ |
| 131         | REAR AIRBAG IMPACT SENSOR RH          |         | 1 | h       | \$898.00     | ✓ |
| 132         | ROOF TOP SIDE AIRBAG IMPACT SENSOR LH |         | 1 | u       | \$691.00     | ✓ |
| 133         | ROOF TOP SIDE AIRBAG IMPACT SENSOR RH |         | 1 | u       | \$691.00     | ✓ |
| 134         | ROOF TOP LINING                       |         | 1 | Tn      | \$2,375.00   | ✓ |
| 135         | REAR FENDER RH                        |         | 1 |         | REPAIR       | ✓ |
| SUB TOTAL   |                                       |         |   |         | \$72,212.00  |   |
| LESS 25%    |                                       |         |   |         | -\$18,053.00 |   |
| PARTS TOTAL |                                       |         |   |         | \$54,159.00  |   |

| NO. | SPECIAL NETT                        | QTY | UNIT S\$ | AMOUNT S\$  |       |
|-----|-------------------------------------|-----|----------|-------------|-------|
| 1   | REAR BUMPER CLIPS                   | 1   |          | Nil \$50.00 | ✓     |
| 2   | REAR BUMPER REVERSE SENSOR          | 1   |          | Tn \$300.00 | 2005m |
| 3   | REAR NUMBER PLATE                   | 1   |          | Nil \$40.00 | 45m   |
| 4   | REAR NUMBER PLATE HOLDER            | 1   |          | \$40.00     |       |
| 5   | REAR END PANEL UPPER COVERING CLIPS | 1   |          | Nil \$30.00 | ✓     |
| 6   | REAR BOOTLID INSULATOR CLIPS        | 1   |          | Nil \$30.00 | ✓     |
| 7   | REAR WINDSCREEN SEALANT             | 1   |          | Nil \$80.00 | 40JA  |
| 8   | FRONT BONNET INSULATOR CLIPS        | 1   |          | Nil \$40.00 | ✓     |
| 9   | FRONT BUMPER CLIPS                  | 1   |          | Nil \$50.00 | ✓     |
| 10  | FRONT NUMBER PLATE                  | 1   |          | Nil \$40.00 | 45m   |
| 11  | FRONT NUMBER PLATE HOLDER           | 1   |          | \$40.00     |       |

Head office

8 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 588047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10.06.2021  
 Vehicle No: SMQ1265C  
 Model: TOYOTA VIOS 1.5E  
 Chassis: MR2B23F3201189856-2019  
 Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: SLZ7785T  
 Date of Accident: 07.06.2021  
 Estimator: TING AN  
 Surveyor:

|           |                                   |   |       |    |            |      |
|-----------|-----------------------------------|---|-------|----|------------|------|
| 12        | FRONT BUMPER UPPER COVER CLIPS    | 1 |       | na | \$30.00    | ✓    |
| 13        | FRONT FENDER INNER LINER CLIPS LH | 1 |       | na | \$30.00    | ✓    |
| 14        | FRONT FENDER INNER LINER CLIPS RH | 1 |       | na | \$30.00    | X    |
| 15        | FRONT WINDSCREEN SEALANT          | 1 |       | na | \$80.00    | 4000 |
| 16        | FRONT RADIATOR COOLANT            | 1 |       | na | \$60.00    | ✓    |
| 17        | FRONT BATTERY                     | 1 | 175SN | na | \$250.00   | 5000 |
| 18        | ROOF TOP LINING CLIPS             | 1 |       | na | \$80.00    | ✓    |
| S/N TOTAL |                                   |   |       |    | \$1,300.00 |      |

## LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

2200  
\$3,000.00

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

1000  
\$2,500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL, REAR FENDER LH, REAR FENDER RH, REAR DOOR LH, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

2600  
\$2,800.00

LABOUR CHARGES REMOVE & REFIX REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT, REAR INNER TRIM, ROOF LINING & ETC. TO EFFECT REPLACE REAR FENDER LH.

\$300.00 2600

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 500

LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC.

\$150.00 1200

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT DASHBOARD & ETC.

\$300.00 2500

LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, REAR SAFETY BELT LH & RH, STEERING WHEEL AIRBAG, FRONT DASHBOARD AIRBAG, FRONT DASHBOARD LOWER AIRBAG RH, ROOF TOP SIDE AIRBAG LH & RH.

\$500.00 4000

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER LH & RH, REAR WHEEL BEARING

\$350.00 2000

### Head office

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

### Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10.06.2021  
Vehicle No: SMQ1265C  
Model: TOYOTA VIOS 1.5E  
Chassis: MR2B23F3201189856-2019  
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SLZ7785T  
Date of Accident: 07.06.2021  
Estimator: TING AN  
Surveyor:

LH & RH, REAR AXLE BEAM & ETC.

TO DIAGNOSE & RESET AIRBAG CONTROL UNIT.

\$300.00 } 2501  
\$150.00 }

TO DIAGNOS FAULT CODE & RESET MEMORY.

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$500.00 2401

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 2

TO REFILL AIRCON GAS.

\$80.00 ✓

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$200.00 601

LABOUR TOTAL \$11,310.00

TING AN TOTAL \$66,769.00

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Company                              |
| Owner ID:                           | 381N                                 |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | SMQ1265C                             |
| Vehicle to be Exported:             | No                                   |
| Intended Deregistration Date:       | 07 Jun 2021                          |
| Vehicle Make:                       | TOYOTA                               |
| Vehicle Model:                      | VIOS 1.5 E (AUTO)                    |
| Primary Colour:                     | Black                                |
| Manufacturing Year:                 | 2019                                 |
| Engine No.:                         | 2NR5395149                           |
| Chassis No.:                        | MR2B23F3201189856                    |
| Maximum Power Output:               | 79.0 kW (105 bhp)                    |
| Open Market Value:                  | \$13,787.00                          |
| Original Registration Date:         | 30 Oct 2019                          |
| First Registration Date:            | 30 Oct 2019                          |
| Transfer Count:                     | 0                                    |
| Actual ARF Paid:                    | \$13,787.00                          |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | Yes                                  |
| PARF Eligibility Expiry Date:       | 29 Oct 2029                          |
| PARF Rebate Amount:                 | \$10,340.00                          |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 29 Oct 2029                          |
| COE Category:                       | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                  | 10                                   |
| QP Paid:                            | \$32,309.00                          |
| COE Rebate Amount:                  | \$27,115.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$37,455.00</b>                   |

The information contained herein is correct as at 07 Jun 2021

OK