

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0484/2021/KS
DATE : 11-Feb-21
WIP : 30834

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/6/2021

YOUR INSURED VEHICLE NO : YP 3293 X

LONPAC INSURANCE BHD

100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

OWNER'S NAME : LIEBHERR-SINGAPORE PTE LTD
ADDRESS : 8 PANDAN AVENUE
SINGAPORE 609384
TELEPHONE : HP +65 92312990
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : BVFPSB0006822109
VEHICLE NO : **SKM 5766 S**
MODEL CODE : A4 1.8 TFSI 8W
MODEL YEAR : 18/3/2014
ENGINE NO : CJE 074582
CHASSIS NO : WAUZZZ8K3EA103354
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Jun-21
PLACE OF ACCIDENT : WOODLAND AVENUE 10, CLOSE TO JUNCTION
OF ADMIRALTY ROAD WEST

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKM 5766 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS AND TEMPERATURE SENSOR.	S/N \$ 360.00	X
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM TO FACILITATE RENEWAL OF LHS WING MIRROR ASSY.	S/N \$ 280.00	✓
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,100.00	1400
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, LHS UPPER A-PILLAR, BONNET AND LHS WING MIRROR COVER.	\$ 4,500.00	3000 4x700 = 2800 Mirror: 200 3000
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,782.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 5766 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 2,560.00	✓	
2	FRONT BUMPER FIXING PARTS <i>Meu</i>	1	\$ 259.00	+	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Meu</i>	1	\$ 228.00	+	
4	FRONT BUMPER AIR GUIDE GRILLE LH <i>Meu</i>	1	\$ 135.00	+	
5	FRONT WHEEL SPOILER LH	1	\$ 51.00	+	
6	FRONT BUMPER GUIDE SECTION LH ?	1	\$ 36.00	?	
7	FRONT FENDER LH <i>Distorted</i>	1	\$ 990.00	✓	
8	FRONT FENDER ATTACHMENT PARTS LH <i>Meu</i>	1	\$ 57.00	+	
9	FRONT FENDER BRACKET LH FRONT <i>Best</i>	1	\$ 53.00	✓	
10	FRONT FENDER BRACKET LH REAR ?	1	\$ 49.00	?	
11	FRONT FENDER BRACE LH <i>Best</i>	1	\$ 118.00	✓	
12	FRONT FENDER CLOSING ELEMENT LH ?	1	\$ 128.00	?	
13	FRONT WHEEL HOUSING LINER LH <i>Meu</i>	1	\$ 240.00	+	
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS LH <i>Meu</i>	1	\$ 45.00	+	
15	FRONT STONE CHIP GUARD LH <i>Meu</i>	1	\$ 73.00	+	
16	FRONT STONE CHIP GUARD ADHESIVE TAPE LH <i>Meu</i>	1	\$ 55.00	+	
17	HEADLIGHT MOUNTING LH ?	1	\$ 118.00	?	
18	HEADLIGHT BRACKET LH ?	1	\$ 106.00	?	
19	HEADLIGHT LH <i>cracked</i>	1	\$ 2,343.00	✓	
20	HEADLIGHT GAS DISCHARGE LH <i>Not new</i>	1	\$ 416.00	+	
SUB TOTAL SPARE PARTS		:	\$ 8,060.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 5766 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HEADLIGHT POWER MODULE	1	\$ 553.00	X
22	HEADLIGHT CONTROL UNIT	1	\$ 1,116.00	+
23	HEADLIGHT RETAINING PLATE	1	\$ 24.00	?
24	HEADLIGHT LIFT CYLINDER LH	1	\$ 210.00	+
25	WING MIRROR MOUNTING LH	1	\$ 1,340.00	—
26	TURN SIGNAL INDICATOR	1	\$ 100.00	—
27	WING MIRROR CAP LH	1	\$ 588.00	✓
28	WINDOW SLOT SEAL	1	\$ 307.00	+
29	ROOF MOLDING LH	1	\$ 629.00	+
30	HEADLIGHT CONTROL UNIT	1	\$ 1,116.00	+
TOTAL SPARE PARTS		:	\$ 14,043.00	
TOTAL LABOUR CHARGES		:	\$ 7,782.00	
GRAND TOTAL		:	\$ 21,825.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan L
SURVEYED DATE : 17/06/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : not authorized, 06 days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT