

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G

SHD9448S

AAD2106-036

Not Notarized
Return B4 part

82889.38

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 JUN 2021

SHD9448S

JTDKB3FU603079459

TOYOTA

PRIUS

08/06/2021

Auto & General

22/03/2019

PART**LIST**

1	PANEL SUB-ASSY, BACK DOOR	\$	R 1,147.80	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>0.01/mfg</i> 925.60	✓
1	STAY ASSY, BACK DOOR, LH	\$	R 242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	R 242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	R 61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	R 61.00	X
1	WEATHERSTRIP, BACK DOOR	\$	R 372.30	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	R 54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	R 54.60	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	R 47.90	✓
1	COVER, BACK DOOR TRIM	\$	R 24.90	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	R 650.30	X
1	LENS AND BODY, REAR LAMP, RH	\$	R 502.00	X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	CM 451.80	✓
1	PANEL SUB-ASSY, QUARTER, RH	\$	R 871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	R 139.80	X
1	COVER, REAR BUMPER	\$	R 442.60	✓
1	COVER, REAR BUMPER, LOWER	\$	R 15.40	✓
1	FILLER, REAR BUMPER EXTENSION, RH	\$	CM 123.70	✓
1	GUARD, REAR BUMPER, CENTER	\$	R 576.30	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	R 332.70	X

TOTAL \$ 7,340.80**25% \$ 1,835.20****\$ 5,505.60****Special Nett**

1SET PARKING AID

1 REAR SPOILER CLIP

\$ R 700.00 X

\$ R 60.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

HD9448S

AAD2106-

1	REAR BUMPER CLIP	\$	na	65.00	same
1	REAR FENDER CLIP	\$	na	66.00	X
1	REAR TAIL LAMP CLIP	\$	na	65.00	X
1	END PANEL INNER TRIM CLIP	\$	na	60.00	X
1	CLIP(FOR REAR DOOR TRIM BOARD)	\$	na	65.00	X
1	BOOT STICKER TRANSCAB	\$	na	100.00	3000
1	BOOT STICKER TELNO	\$	na	100.00	3000
2	WINDSCREEN SEALANT	\$	na	150.00	X
1	WINDSCREEN MOULDING	\$	na	200.00	X
1	WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	X
TOTAL		\$		1,001.00	

TOTAL PARTS \$ 8,543.40**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	4400
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,800.00	3000
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	na	170.00	X
TOTAL		\$	4,790.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Over All Total \$ 18,839.00**(PART-BY-PART) Repair Days****10 Days****2 days**