

ASSIGNED BY:

62

# ASSIGNMENT

CTI

From:

Date:

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

at Workshop m/s Boon Siew

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Cár / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Other (\$)

Survey Fee:

Transportation:

3 + RS. SI

Photos

Other

**BOON SIEW SINGAPORE PTE LTD**

370 Ubi Road 3 Singapore 408651

255 Alexandra Road Singapore 159937

Tel: +65 6339 9002

Website: +65 6333 4332

**QUOTATION**GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD  
SPRINGLEAF TOWER  
SINGAPORE 079909

Registration No : FBL8374G

Chassis No : JH2RC90A0HK102496

Model : NC750XAH

Owner's Name : LEE CHIT HWA

Ins Policy No. :

Date of Accident :

Document No. : SQT0000110

Date : 8. Jun 2021

Customer No. : CU00001220

Svc Advisor :

Engine No : RC88E5011356

Date | Time : 8. Jun 2021 9:29:57 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

| Item            | Description                                                                              | Qty | Unit Price | Disc % | Amount         | 0% GST Amount | Amount incld GST |
|-----------------|------------------------------------------------------------------------------------------|-----|------------|--------|----------------|---------------|------------------|
|                 | DATE OF ACCIDENT:12/05/2021                                                              |     |            |        |                |               |                  |
|                 | POLICY NO.:5107722391-02                                                                 |     |            |        |                |               |                  |
|                 | DATE TOW/DRIVE IN:                                                                       |     |            |        |                |               |                  |
|                 | SURVEYOR NAME: LKK / GUO QIANG                                                           |     |            |        |                |               |                  |
|                 | DATE SURVEY:17/06/21                                                                     |     |            |        |                |               |                  |
|                 | AUTHORISED BY:                                                                           |     |            |        |                |               |                  |
|                 | EXCESS:                                                                                  |     |            |        |                |               |                  |
|                 | 3RD PARTY VEHICLE NO.:GBD3104U                                                           |     |            |        |                |               |                  |
|                 | CASE REF.:SNM21D203315/C02/GBD3104U/lewic                                                |     |            |        |                |               |                  |
| 070798          | TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT, REALIGN AFFECTED PORTION TO ALIGNMENT | 3   | 350.00     |        | 1050.00        | 73.50         | 1123.50          |
| 060698          | USING HONDA MOTORCYCLE COMMUNICATION SYSTEM (MCS) TO ERASE/RESET MEMORY. NETT            | 2.4 | 50.00      |        | 120.00         | 8.40          | 128.40 ✓         |
| WSP006          | SUPPLY RR NUMBER PLATE(S) NETT / SCR                                                     | 0.5 | 50.00      |        | 25.00          | 1.75          | 26.75            |
| WSP010          | KAPPA TOP BOX., 47L ?                                                                    | 1   | 193.00     |        | 193.00         | 13.51         | 206.51           |
| WSP010          | TOP BOX RACK / BT.                                                                       | 1   | 167.00     |        | 167.00         | 11.69         | 178.69           |
|                 | <b>Sum Labor</b>                                                                         |     |            |        | <b>1555.00</b> | <b>108.85</b> | <b>1.663.85</b>  |
| 33701-MKA-D81   | UNIT, TAIL LIGHT ✓ CA                                                                    | 1   | 186.30     |        | 186.30         | 13.04         | 199.34           |
| 33720-MKA-D81   | LIGHT ASSY LICENS ?                                                                      | 1   | 59.20      |        | 59.20          | 4.14          | 63.34            |
| 80100-MKA-D80   | FENDER A, RR ? ✓ CA                                                                      | 1   | 53.50      |        | 53.50          | 3.75          | 57.25            |
| 80101-MKA-D80   | STAY, FENDER A ?                                                                         | 1   | 70.00      |        | 70.00          | 4.90          | 74.90            |
| 80105-MKA-D80   | FENDER B, RR ?                                                                           | 1   | 167.90     |        | 167.90         | 11.75         | 179.65           |
| 77211-MKA-D80ZA | COWL SET ILLUSTR*TYPE1* / RE                                                             | 1   | 56.00      |        | 56.00          | 3.92          | 59.92            |
| 77216-MKA-D80ZA | COWL, L SEA*R305C* / RE                                                                  | 1   | 171.40     |        | 171.40         | 12.00         | 183.40           |
| 77340-MJJ-D30ZC | GRIP L, RR*NH303M* / BR                                                                  | 1   | 154.70     |        | 154.70         | 10.83         | 165.53           |
|                 | <b>Sum Item</b>                                                                          |     |            |        | <b>919.00</b>  | <b>64.33</b>  | <b>983.33</b>    |

Survey By

Printed on 17/6/2021 2:21:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

# QUOTATION

ON SIEW SINGAPORE PTE LTD

70 Ubi Road 3 Singapore 408651

255 Alexandra Road Singapore 159937

Tel: +65 6339 9002

Website: +65 6333 4332

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD  
SPRINGLEAF TOWER  
SINGAPORE 079909  
Registration No : FBL8374G  
Chassis No : JH2RC90A0HK102496  
Model : NC750XAH  
Owner's Name : LEE CHIT HWA  
Ins Policy No. :  
Date of Accident :

Document No. : SQT0000110  
Date : 8. Jun 2021  
Customer No. : CU00001220  
Svc Advisor :  
Engine No : RC88E5011356  
Date | Time : 8. Jun 2021 9:29:57 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Page 2

| Item        | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-------------|-------------|-----|------------|--------|--------|---------------|------------------|
| Date & Time | 17/6/21     |     |            |        |        |               |                  |
| Excess      |             |     |            |        |        |               |                  |
| Status      |             |     |            |        |        |               |                  |
| Signature   | Quo Q:at    |     |            |        |        |               |                  |

Total Amount 2,474.00 173.18 2,647.18  
Total (Inclusive of GST) 2,647.18

8288 282  
1 Day.  
After repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 17/6/2021 2:21:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.