



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21006639/Euf3n2	
			Date: 26/07/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHF 120K	Veh. Inspected	SJC 1963E
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/21/2019	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	11/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	BMW X1	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WBA72AA0705R42141	Colour	WHITE
	Odometer	14764 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/50 R17	MICHELIN	5 mm
	L/H Front Tyre	215/50 R17	MICHELIN	5 mm
	R/H Rear Tyre	215/50 R17	MICHELIN	5 mm
	L/H Rear Tyre	215/50 R17	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/06/2021	Inspection Date	29/06/2021
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	