



Final Report

Estimate No. : **b1 58645**
Date Estimated : **10/06/2021**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -

Yap Chue Chye
46 Lengkong Tujoh
#01-27

Singapore 417396

- ACCOUNT -

303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJC1963E	WBA72AA0705R421	27/07/2020	X1 sDrive20i	5749

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
Make good rear bumper panel and attachments	850.00	0.00	850.00
To spray paint bumper rear panel	986.00	0.00	986.00
To check electrical wiring system and lighting at the rear section.	168.00	0.00	168.00
Sundries.	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET WHITE	1.95	10.00	0.00	19.50
REAR BUMPER BOTTOM TRIM PANEL (M PD	297.90	1.00	0.00	297.90

SUPPLEMENTARY ITEMS

Total Labour :	2,084.00
Total Parts :	317.40
Total Labour & Parts :	2,401.40
Deduction for Excess :	
Total Repair Costs less Excess:	2,401.40
GST @7%:	168.10
<u>Grand Total :</u>	<u>2,569.50</u>

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 58645**
Date Estimated : **10/06/2021**
Prepared By : **Foong Shiuh Jye**

- ESTIMATE REPAIR FOR -
Yap Chue Chye
46 Lengkong Tujoh
#01-27

Singapore 417396

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJC1963E	WBA72AA0705R421	27/07/2020	X1 sDrive20i	5749

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING RIVET WHITE	1.95	10.00	0.00	19.50 <i>nec</i>
-------------------------	------	-------	------	------------------

SUPPLEMENTARY ITEMS

Total Labour :

Total Parts :

19.50