

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 11 June 2021

TO

Attn: Mr. Bryan

Tel: 97541858

VEHICLE NO : FV 9524J

Honda CB400

ACCIDENT DATE: 7 June 2021

Description	Qty	Quotation \$
1 Balancer cut o/s H/S H/H	1 set	185.00 ✓ 92.50
2 Handle Bar 2 distance	1	185.00 ✓
3 Mirror H/H	1 set	210.00 X
4 Fork Tube 2 1/2	1 set	1,200.00 ✓
5 Fork Oil Seal 2 H/H	1	125.00 ✓
6 Crash Bar cut	1 set	280.00 ✓
7 Rear Tail Panel H/H	1	195.00 X
8 Blue Flame Exhaust End Can 3/2	1	1,600.00 X
9 Starter Switch Assy broken	1	220.00 ✓
10 Rear Mudguard H/H	1	210.00 X
11 Number Plate Reflector H/H	1	150.00 X
12. Rear mudguard broken 220.00 ✓		
Sub-Total		4,560.00
Less 10%		456.00
Sub-Total		4,104.00

13. ~~Headlamp Assy~~

14. ~~Crash Bar~~

9-260-2

LR Auto Consultants notice

The Repairer of the following:

- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO : FV 9524J

Honda CB400

Nett items

- 1 Towing fee ~~HN~~
- 2 Remove & replace necessary parts, align & etc
- 3 Remove & replace fork tube & top up fork oil
- 4 Decal body sticker ~~HN~~

40.00 X
200.00 150/-
140.00 80/-
250.00 X

230.00

Sub-Total
Nett Total

630.00
4,734.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you.

SG 98 MOTOR PTE LTD

2122.25

Supp 432.00

2554.25

4/s 2000/-

14/06/22 @ 1730 hrs

Nett Amount

2/s 3 days

mya

2/s Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 22th June 2021

To : LKK

By Fax:

Attn : Bryan

Tel :

VEHICLE NO : FV 9524J

Honda CB400

ACCIDENT DATE: 7/6/2021


	Description	Qty	Quotation \$
	Supplementary Items		
1	Front Mudguard <i>broken</i>	1	220.00 ✓
2	Head Lamp Assembly <i>Crack (Dent)</i>	1 set	260.00 ✓
Total			480.00

10% 432.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you


SG 98 MOTOR PTE LTD



LKK Ando

