



M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

Estimate No: ES2100055
Date: 10 Jun 2021
Policy No:
Veh Reg No: GBF9435P
Make/Model: TOYOTA DYNA 3.0
MANUAL
Chassis No: KDY2318025312
Engine No: 1KD2621423
Reg. Date: 20/04/2017

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 08/06/2021
TP Veh Reg No: GBC2246E

Not Authorized
11 Day &
Running After Claim
20 days

Estimate Repair Cost to Vehicle No :GBF9435P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT NUMBER PLATE	50.00	1 PC	50.00	40.00
2 FRONT TYRE - LH	280.00	1 PC	280.00	?
3 FRONT TYRE - RH	280.00	1 PC	280.00	X
4 FRONT WHEEL RIM - LH	380.00	1 PC	380.00	✓
5 FRONT WHEEL RIM - RH	380.00	1 PC	380.00	X
6 FRONT WINDSCREEN RUBBER	198.15	1 PC	198.15	50.00
7 REAR WHEEL RIM - LH (OUTSIDE)	200.00	1 PC	200.00	✓
8 REAR WHEEL RIM - RH (OUTSIDE)	200.00	1 PC	200.00	✓
9 REAR TYRE - LH (OUTSIDE)	100.00	1 PC	100.00	?
10 REAR TYRE - RH (OUTSIDE)	100.00	1 PC	100.00	?
11 FRONT WINDSCREEN IU BRACKET	25.00	1 PC	25.00	✓
			2,193.15	2,193.15
Spare Parts				
12 BRAKE AIR TANK	380.15	1 PC	380.15	?
13 ENGINE MOUNTING	585.00	1 PC	585.00	?
14 BRAKE OIL	40.00	1 PC	40.00	?
15 CABIN STICKER - LH	350.00	1 PC	350.00	✓
16 FOG LAMP - LH	195.05	1 PC	195.05	X
17 FOG LAMP - RH	915.05	1 PC	915.05	✓
18 FOG LAMP BRACKET - LH	85.60	1 PC	85.60	X
19 FOG LAMP BRACKET - RH	85.60	1 PC	85.60	✓
20 FRONT BUMPER	572.80	1 PC	572.80	✓
21 FRONT BUMPER FOG LAMP GARNISH - LH	85.00	1 PC	85.00	X
22 FRONT BUMPER FOG LAMP GARNISH - RH	85.00	1 PC	85.00	✓
23 FRONT BUMPER REINFORCEMENT	342.80	1 PC	342.80	✓
24 FRONT CORNER FENDER - LH	223.90	1 PC	223.90	X
25 FRONT CORNER FENDER - RH	223.90	1 PC	223.90	X
26 FRONT CROSS MEMBER	750.00	1 PC	750.00	?
27 FRONT DOOR - LH	1,268.50	1 PC	1,268.50	✓
28 FRONT DOOR - RH	1,268.50	1 PC	1,268.50	✓
29 FRONT DOOR HINGE BOTTOM - LH	82.50	1 PC	82.50	X
30 FRONT DOOR HINGE BOTTOM - RH	82.50	1 PC	82.50	✓
31 FRONT DOOR HINGE TOP - LH	82.50	1 PC	82.50	X
32 FRONT DOOR HINGE TOP - RH	82.50	1 PC	82.50	X
33 FRONT DOOR INNER TRIM - LH	420.00	1 PC	420.00	X
34 FRONT DOOR INNER TRIM - RH	420.00	1 PC	420.00	?

(Bill)



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 08/06/2021
TP Veh Reg No: GBC2246E

Estimate No: ES2100055
Date: 10 Jun 2021
Policy No:
Veh Reg No: GBF9435P
Make/Model: TOYOTA DYNA 3.0
MANUAL
Chassis No: KDY2318025312
Engine No: 1KD2621423
Reg. Date: 20/04/2017

Estimate Repair Cost to Vehicle No :GBF9435P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 FRONT DOOR LOCK - LH	320.00	1 PC	320.00 X	
36 FRONT DOOR LOCK - RH	320.00	1 PC	320.00 X	
37 FRONT DOOR MOTOR - LH (REGULAR)	350.00	1 PC	350.00 X	
38 FRONT DOOR MOTOR - RH (REGULATOR)	350.00	1 PC	350.00	
39 FRONT DOOR OUTER HANDLE - LH	250.15	1 PC	250.15	
40 FRONT DOOR OUTER MOULDING - LH	145.00	1 PC	145.00	
41 FRONT DOOR OUTER MOULDING - RH	145.00	1 PC	145.00 X	
42 FRONT DOOR PILLAR - LH	780.15	1 PC	780.15	
43 FRONT DOOR PILLAR - RH	780.15	1 PC	780.15 X	
44 FRONT DOOR REGULATOR - LH	280.00	1 PC	280.00 X	
45 FRONT DOOR REGULATOR - RH	280.00	1 PC	280.00	
46 FRONT DOOR SIDE COVER - LH	85.60	1 PC	85.60	
47 FRONT DOOR INNER GLASS SIDE MIRROR - RH	315.00	1 PC	315.00 X	
48 FRONT DOOR INNER GLASS SIDE RUBBER - LH	75.85	1 PC	75.85	
49 FRONT DOOR SIDE RUBBER - RH	75.85	1 PC	75.85	
50 FRONT DOOR STICKER - LH	25.00	1 PC	25.00	
51 FRONT DOOR STICKER - RH	25.00	1 PC	25.00	
52 FRONT DOOR WEATHERSTRIP - LH	125.60	1 PC	125.60	
53 FRONT DOOR WEATHERSTRIP - RH	125.60	1 PC	125.60	
54 FRONT FENDER - LH	195.00	1 PC	195.00	
55 FRONT FENDER - RH	195.00	1 PC	195.00 X	
56 FRONT GRILLE	434.20	1 PC	434.20	
57 FRONT GRILLE CLIPS	30.00	1 PC	30.00	
58 FRONT GRILLE LOGO	95.15	1 PC	95.15	
59 FRONT HEADLAMP - LH	858.40	1 PC	858.40	
60 FRONT HEADLAMP - RH	858.40	1 PC	858.40	
61 FRONT KNUCKLE ARM - LH	641.70	1 PC	641.70	
62 FRONT KNUCKLE ARM - RH	641.70	1 PC	641.70	
63 FRONT LOWER ARM - LH	320.00	1 PC	320.00	
64 FRONT LOWER ARM - RH	320.00	1 PC	320.00	
65 FRONT PANEL	385.00	1 PC	385.00	
66 FRONT PANEL CENTRE GARNISH	185.60	1 PC	185.60	
67 FRONT PANEL SIDE GARNISH - LH	85.60	1 PC	85.60 X	
68 FRONT PANEL SIDE GARNISH - RH	85.60	1 PC	85.60	
69 FRONT SHOCK ABSORBER - LH	285.90	1 PC	285.90	
70 FRONT SHOCK ABSORBER - RH	285.90	1 PC	285.90	
71 FRONT SIDE MIRROR - LH	315.00	1 PC	315.00	
72 FRONT SIDE MIRROR GARNISH - LH	135.15	1 PC	135.15	



160 Sin Ming Drive #02-17/18-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 08/06/2021
TP Veh Reg No: GBC2246E

Estimate No: ES2100055
Date: 10 Jun 2021
Policy No:
Veh Reg No: GBF9435P
Make/Model: TOYOTA DYNA 3.0
MANUAL
Chassis No: KDY2318025312
Engine No: 1KD2621423
Reg. Date: 20/04/2017

Estimate Repair Cost to Vehicle No :GBF9435P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
73 FRONT STEERING BOX	880.15	1 PC	<i>cm</i> 880.15	✓
74 FRONT STEERING RACK	2,800.00	1 PC	2,800.00	?
75 FRONT STEP GARNISH - LH	185.00	1 PC	<i>cm</i> 185.00	—
76 FRONT STEP GARNISH - RH	185.00	1 PC	<i>cm</i> 185.00	—
77 FRONT STEP INNER PANEL - RH	265.00	1 PC	<i>cm</i> 265.00	X
78 FRONT UPPER ARM - LH	475.20	1 PC	475.20	?
79 FRONT UPPER ARM - RH	475.20	1 PC	475.20	?
80 FRONT WHEEL BEARING - LH	375.20	1 PC	375.20	?
81 FRONT WHEEL BEARING - RH	375.20	1 PC	375.20	?
82 FRONT WHEEL RIM CAP - LH	100.00	1 PC	<i>cm</i> 100.00	X
83 FRONT WINDSCREEN	650.00	1 PC	<i>cm</i> 650.00	—
84 FRONT WINDSCREEN GLASS MOULDING	<i>nn</i> 108.50	1 PC	108.50	X
85 FRONT WIPER ARM - LH	90.05	1 PC	<i>cm</i> 90.05	X
86 FRONT WIPER ARM - RH	90.05	1 PC	<i>cm</i> 90.05	X
87 FRONT WIPER BLADE - LH	30.00	1 PC	<i>cm</i> 30.00	X
88 FRONT WIPER BLADE - RH	30.00	1 PC	<i>cm</i> 30.00	X
89 FRONT WIPER PANEL	285.10	1 PC	<i>cm</i> 285.10	✓
90 FUSE BOX	280.15	1 PC	280.15	?
91 FUSE BOX BRACKET	135.15	1 PC	135.15	?
92 HEADLAMP LOWER RUBBER - LH	40.00	1 PC	<i>cm</i> 40.00	—
93 HEADLAMP LOWER RUBBER - RH	40.00	1 PC	<i>cm</i> 40.00	—
94 REAR CANOPY	<i>nd</i> 1,200.00	1 PC	<i>cm</i> 1,200.00	350.00
95 REAR CARGO SIDE DOOR HINGE	250.00	1 SET	<i>cm</i> 250.00	—
96 REAR CARGO SIDE STOPPER RUBBER - LH (FRONT)	40.00	1 PC	40.00	?
97 REAR CARGO SIDE STOPPER RUBBER - LH (REAR)	40.00	1 PC	40.00	?
98 REAR DOOR PILLAR - LH	780.15	1 PC	<i>cm</i> 780.15	✓
99 REAR TAILLAMP - LH	285.00	1 PC	<i>cm</i> 285.00	X
100 REAR TYRE FENDER - LH (FRONT)	180.00	1 PC	<i>cm</i> 180.00	X
101 REAR TYRE FENDER - LH (REAR)	180.00	1 PC	<i>cm</i> 180.00	X
102 STABILIZER BAR CENTRE	480.15	1 PC	480.15	?
103 STEERING BOX BALL JOINT	280.15	1 PC	280.15	?
104 WIPER LINK	215.20	1 PC	<i>cm</i> 215.20	X
105 WIPER MOTOR	445.10	1 PC	<i>cm</i> 445.10	X
106 FRONT DOOR SIGNAL LAMP - LH	165.15	1 PC	<i>cm</i> 165.15	—
107 FRONT DOOR SIGNAL LAMP - RH	165.15	1 PC	<i>cm</i> 165.15	—
108 REAR AXLE SUP - LH	2,200.00	1 PC	2,200.00	?
109 REAR AXLE SUP - RH	<i>Repair</i> 2,200.00	1 PC	2,200.00	X
110 REAR WHEEL BEARING - LH	250.00	1 PC	250.00	?



YEE AUTO PTE LTD
 160 Sin Ming Drive #02-17/07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopte ltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16
 Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 08/06/2021
 TP Veh Reg No: GBC2246E

Estimate No: ES2100055
 Date: 10 Jun 2021
 Policy No:
 Veh Reg No: GBF9435P
 Make/Model: TOYOTA DYNA 3.0
 MANUAL
 Chassis No: KDY2318025312
 Engine No: 1KD2621423
 Reg. Date: 20/04/2017

Estimate Repair Cost to Vehicle No :GBF9435P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
111 REAR WHEEL BEARING - RH	250.00	1 PC	250.00	?
112 FRONT MUDFLAP - LH	380.15	1 PC	380.15	✓
113 BODY STICKER	Bill ? 1,200.00	1 PC	1,200.00	✓
114 AIRCON BLOWER COVER	684.15	1 PC	684.15	?
115 REAR CARGO SAFETY GATE - LH	520.00	1 PC	520.00	✓
116 REAR CARGO SAFETY GATE - RH	520.00	1 PC	520.00	✓
117 REAR CARGO SIDE DOOR - LH	850.15	1 PC	850.15	✓
118 REAR CARGO SIDE DOOR - RH	850.15	1 PC	850.15	x
			42,339.70	42,339.70
Labour				
119 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	3,000.00	1 JOB	3,000.00	2400
120 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	3,000.00	1 JOB	3,000.00	1800
121 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	350.00	1 JOB	350.00	180
122 TO REMOVE/REPLACE FRONT UNDERCARRIAGE LABOUR.	600.00	1 PC	600.00	2400
123 TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	60
124 LABOUR TO REMOVE AND REPLACE FRONT DOOR COMPONENTS.	200.00	1 JOB	200.00	1200
125 LABOUR TO REMOVE AND REPLACE FRONT DASHBOARD.	600.00	1 JOB	600.00	2500
126 TO TOW VEHICLE TO WORKSHOP.	180.00	1 JOB	180.00	?
127 WHEEL ALIGNMENT	120.00	1 T	120.00	1000
128 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	400
			8,350.00	8,350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL: SINGAPORE DOLLAR FIFTY SIX THOUSAND ONE HUNDRED EIGHTY FOUR AND CENTS SIXTY FIVE ONLY

Total S\$ 52,882.85
 Add GST @ 7% 3,701.80
 Total Amount Payable S\$ 56,584.65

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE