

Our Job Ref No : 305472969
Date : 15/06/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr NAZ
Vehicle Reg No. : SHD4830D CTPL
Fax : 10.06.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC --- SGY6507B
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$340.62
 - (b) Labour Charges \$1,240.00
 - Total for Part-By-Part Repair Cost \$1,580.62**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : MS. LOKE YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 16/6/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.06.2021

REPAIR ESTIMATE

Time: 10:37:45

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305472969
REGN NO : SHD4830D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 13.02.2020
DATE/TIME IN : 10.06.2021 08:10
ACCIDENT DATE : 10.06.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0302-2017-A	FUEL TANK LID (PETROL ONL	1	15.00	10.00	13.50	✓ NEC
0002 03-01-0104-2137-G	CAP ASSY-WHEEL HUB	1	346.40	20.00	277.12	✓ SR
0003 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00	✓ NEC

SUB-TOTAL : 340.62

JOB NATURE

0000 PB	PANEL BEATING SHD4830D	700.00	✓
0001 SP	SPRAYPAINT CHARGE	500.00	✓
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	✓

SUB-TOTAL : 1,240.00

TOTAL : 1,580.62

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4830D

Date: 11/06/21

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR FENDER LH			\$1,768.30
1	REAR BUMPER SIDE BRACKET LH			\$55.80
1	RR WHEEL HUB CAP LH			\$346.40
	SUB TOTAL			\$2,651.90
	LESS 20%			\$530.38
	DISCOUNTED TOTAL			\$2,121.52
1	REAR FENDER PETROL STICKER			\$15.00
1	REAR BUMPER RUBBER MAT			\$50.00
				\$65.00
	Labour Charge			
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE			\$600.00
	TUFF KOTE			\$60.00
	TOTAL LABOUR			\$1,360.00
	ESTIMATE TOTAL			\$3,546.52

XR
XSVC
XR
?XSVC
—SR

Less 10%
\$ 13.50

Nett CNEC
Nett CNEC

700
500
KD

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK

11/6/2021 1530

P/R

2 days

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey on a "without prejudice" basis
- To accept the final repair cost
- Supply of materials to be used in repair and is subject to final approval by the insurance company

Acknowledged by Repairer:

Signature:

Date: