

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4830D

Date: 11/06/21

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$459.40	XR
10	REAR BUMPER CLIPS			\$22.00	XSUL
1	REAR FENDER LH			\$1,768.30	XR
1	REAR BUMPER SIDE BRACKET LH			\$55.80	?
1	RR WHEEL HUB CAP LH			\$346.40	✓ SR
	SUB TOTAL			\$2,651.90	
	LESS 20%			\$530.38	
	DISCOUNTED TOTAL			\$2,121.52	
1	REAR FENDER PETROL STICKER			\$15.00	Nett CNEC
1	REAR BUMPER RUBBER MAT			\$50.00	Nett CNEC
				\$65.00	
	Labour Charge				
	PANEL BEATING			\$700.00	700
	SPRAY PAINTING CHARGE			\$600.00	500
	TUFF KOTE			\$60.00	40
	TOTAL LABOUR			\$1,360.00	
	ESTIMATE TOTAL			\$3,546.52	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK

11/6/2021 1530

P/R

2 Days

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party claim will be on "No Fault" basis
- To be settled by the insurance company
- To be settled by the insurance company and is subject to the insurance company's decision

Acknowledged by Repairer:

Signature:

Date: