

(08/11/13) Wef

ASS. REC. BY: P. S. S. S.

REF:

CS/TM121006648/RVf3

8395

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 2889Jat Workshop m/s DASH AUTOMOTIVEof 31, CORPORATION RD

Insured:

TM1

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

Veh No:

SHB 2889JYr Regn: 2020 / 04Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Accent 1.6c.c. 1580

Colour:

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

44 435

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH C851CV LU 184 582Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

11/06/21

D.O.I.

14/06/21

Survey held at

DASH AUTODes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

) S + RS SI

: Interview (\$

) Photos



: Tech. Invs (\$

) Others

Report Format :

Lump Sum / I.B.I. (\$

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

12/06/2021 15:24

JOB-NO: 50113440

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 3

VEHICLE DETAILS

LICENSE NO: SHB2889J TRANS: AUTO
 MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI
 OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD
 JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: KMHC851CVLU184582
 ENGINE: G4LEKU391114

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	1,800.00	0.00	1,800.00	Y		1800 900
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	220.00	0.00	220.00	Y		220 100
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE REPAIR	1.00	450.00	0.00	450.00	Y		450 100
4 TO TRANSFER REAR BOOT MECHANISM TO NEW BOOT AND PERFORM WATER SEEPAGE TEST	1.00	220.00	0.00	220.00	Y		220 60
5 TO REMOVE AND REFIT REAR BIG AND SMALL WINDSCREEN GLASS TO ENABLE BODYWORK REPAIR	1.00	250.00	0.00	250.00	Y		250 200
6 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	250.00	0.00	250.00	Y		250 100
7 TO CHECK AND REPAIR WIRE HARNESS	1.00	280.00	0.00	280.00	Y		280 60
8 TO REFIT REAR REVERSE SENSOR	1.00	150.00	0.00	150.00	Y		150 60
9 TO RESPRAY REAR REVERSE SENSOR	1.00	250.00	0.00	250.00	Y		250 X
10 TO RESPRAY REAR TAILGATE PANEL	1.00	250.00	0.00	250.00	Y		250 200
11 TO RESET, REALIGN AND RECALIBRATE REAR BLIND SPOT COLLISION UNIT AND SENSORS AFTER REMOVE AND REFIT REAR BUMPER	1.00	350.00	0.00	350.00	Y		350 80
12 TO REMOVE AND REFIT SPARE WHEEL PANEL TRIM AND FENDER INNER TRIM	1.00	300.00	0.00	300.00	Y		300 40
13 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		250 200
14 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		250 200
15 TO RESPRAY REAR BUMPER CENTER MOULDING ASSY	1.00	250.00	0.00	250.00	Y		250 100
16 TO RESPRAY REAR BUMPER LOWER CENTER MOULDING	1.00	250.00	0.00	250.00	Y		250 100
17 TO RESPRAY REAR FLOOR PANEL	1.00	250.00	0.00	250.00	Y		250 200
18 MOUNT WORKBENCH - TO REALIGNMENT CHASSIS AND REPAIR ACCIDENT AREA	1.00	350.00	0.00	350.00	Y		350 X
19 TO VACUUM GLASS SHARD AND WASH CARPET, REAR SEAT	1.00	200.00	0.00	200.00	Y		200 X
20 TO RESPRAY REAR TAILGATE GARNISH	1.00	250.00	0.00	250.00	Y		250 X
21 TO RESPRAY REAR SPOILER	1.00	250.00	0.00	250.00	Y		250 100
22 TO REAPPLY SEAL JOINT ON WELDING AFFECTED AREAS	1.00	250.00	0.00	250.00	Y		250 60

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
TOTAL:		7,320.00	0.00	7,320.00			
MATERIALS							
1 REAR BUMPER COVER <i>de/</i>	1.00	759.40	151.88	607.52	L	Y	
2 REAR BUMPER CENTER MOULDING ASSY <i>cm/</i>	1.00	486.86	97.37	389.49	L	Y	
3 REAR BUMPER TOWING COVER <i>X</i>	1.00	86.95	17.39	69.56	L	Y	
4 REAR RH BUMPER REFLECTOR <i>90/</i>	1.00	98.68	19.74	78.94	L	Y	
5 REAR BUMPER CENTER UNDER COVER <i>cm/</i>	1.00	289.87	57.97	231.90	L	Y	
6 REAR RH SIDE BUMPER UNDER COVER <i>X</i>	1.00	295.68	59.14	236.54	L	Y	
7 REAR RH BEAM LOWER MOUNTING BRACKET <i>cm/</i>	1.00	129.81	25.96	103.85	L	Y	
8 REAR FOG LAMP ASSY <i>X</i>	1.00	390.65	78.13	312.52	L	Y	
9 REAR BUMPER REINFORCEMENT <i>cm/</i>	1.00	482.54	96.51	386.03	L	Y	
10 REAR RH BUMPER REINFORCEMENT BRACKET <i>bt/</i>	1.00	297.85	59.57	238.28	L	Y	
11 REAR LH BUMPER REINFORCEMENT BRACKET <i>X</i>	1.00	297.85	59.57	238.28	L	Y	
12 SMART KEY ANTENNA ASSY <i>cm/</i>	1.00	195.59	39.12	156.47	L	Y	
13 REAR LH SIDE BUMPER UNDER COVER <i>X</i>	1.00	292.25	58.45	233.80	L	Y	
14 REAR BUMPER RETAINER <i>X</i>	1.00	178.76	35.75	143.01	L	Y	
15 REAR LICENCE PLATE LAMP ASSY <i>cm/bt/pc/</i>	2.00	373.98	74.80	299.18	L	Y	
16 REAR BUMPER LOWER CENTER MOULDING <i>cut/</i>	1.00	198.69	39.74	158.95	L	Y	
17 REAR BUMPER WIRE HARNESS <i>X</i>	1.00	385.93	77.19	308.74	L	Y	
18 REAR TAILGATE PANEL ASSY <i>bt/</i>	1.00	2,580.40	516.08	2,064.32	L	Y	
19 REAR BOOT WEATHERSTRIP <i>re/</i>	1.00	295.56	59.11	236.45	L	Y	
20 REAR BOOT LOCK ASSY <i>cut/</i>	1.00	394.95	78.99	315.96	L	Y	
21 REAR TAILGATE HYBRID EMBLEM <i>re/</i>	1.00	58.60	11.72	46.88	L	Y	
22 REAR TAILGATE IONIQ EMBLEM <i>re/</i>	1.00	55.90	11.18	44.72	L	Y	
23 REAR TAILGATE HYUNDAI EMBLEM <i>re/</i>	1.00	65.50	13.10	52.40	L	Y	
24 REAR TAILGATE WINDSCREEN UPPER MOULDING <i>re/</i>	1.00	193.89	38.78	155.11	L	Y	
25 REAR TAILGATE WINDSCREEN LOWER MOULDING <i>re/</i>	1.00	189.63	37.93	151.70	L	Y	
26 REAR TAILGATE WIRING ASSY <i>cut/</i>	1.00	486.23	97.25	388.98	L	Y	
27 REAR TAILGATE OUTER DOOR PULL HANDLE <i>cut/</i>	1.00	129.64	25.93	103.71	L	Y	
28 REAR TAILGATE PANEL TRIM ASSY <i>cm/</i>	1.00	348.96	69.79	279.17	L	Y	
29 REAR RH TAILGATE LAMP COVER <i>mis/</i>	1.00	139.79	27.96	111.83	L	Y	
30 REAR TAILGATE CENTER TRIM ASSY <i>cut/</i>	1.00	289.72	57.94	231.78	L	Y	
31 REAR TAILGATE UPPER TRIM ASSY <i>X</i>	1.00	228.99	45.80	183.19	L	Y	
32 REAR RH SIDE TAILGATE FRAME TRIM ASSY <i>X</i>	1.00	214.23	42.85	171.38	L	Y	
33 REAR LH SIDE TAILGATE FRAME TRIM ASSY <i>X</i>	1.00	214.23	42.85	171.38	L	Y	
34 REAR LUGGAGE CENTER TRAY ASSY <i>cut/</i>	1.00	586.30	117.26	469.04	L	Y	
35 REAR RH LUGGAGE SIDE TRAY ASSY <i>de/</i>	1.00	548.10	109.62	438.48	L	Y	
36 REAR RH LUGGAGE SIDE TRIM ASSY <i>de/</i>	1.00	789.60	157.92	631.68	L	Y	
37 BOOT REFLECTOR LAMP LH <i>cm/</i>	1.00	745.66	149.13	596.53	L	Y	
38 BOOT REFLECTOR LAMP RH <i>cm/</i>	1.00	745.66	149.13	596.53	L	Y	
39 TAILLAMP LH <i>X</i>	1.00	796.55	159.31	637.24	L	Y	
40 TAILLAMP RH <i>cm/</i>	1.00	796.55	159.31	637.24	L	Y	
41 REAR LUGGAGE COVERING BOARD ASSY <i>X</i>	1.00	385.96	77.19	308.77	L	Y	
42 REAR LUGGAGE COVERING BOARD TOP MAT <i>tom/</i>	1.00	258.94	51.79	207.15	L	Y	
43 REAR TAILGATE GARNISH <i>?</i>	1.00	149.86	29.97	119.89	L	Y	
44 REAR TAILGATE RELEASE HANDLE ASSY <i>X</i>	1.00	125.67	25.13	100.54	L	Y	
45 REAR TAILGATE GARNISH STRIP <i>?</i>	1.00	118.44	23.69	94.75	L	Y	
46 REAR TAILGATE GARNISH LOWER (SWITCH HOUSING) <i>?</i>	1.00	188.93	37.79	151.14	L	Y	
47 BACK VIEW CAMERA ASSY <i>X</i>	1.00	899.90	179.98	719.92	L	Y	
48 REAR SPOILER ASSY <i>cm/</i>	1.00	785.40	157.08	628.32	L	Y	
49 HIGH MOUNT STOP LAMP ASSY <i>cm/</i>	1.00	468.99	93.80	375.19	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
50 REAR END PANEL <i>bt</i>	1.00	688.30	137.68	550.64	L	Y	
51 REAR END PANEL TRIM BOARD <i>de</i>	1.00	340.50	68.10	272.40	L	Y	
52 REAR TAILGATE LOWER WINDSCREEN ASSY <i>bro</i>	1.00	588.87	117.77	471.10	L	Y	
53 REAR FLOOR PAN ASSY <i>repar</i>	1.00	788.96	157.79	631.17	L	Y	
54 REAR LH FENDER LINER <i>x</i>	1.00	285.60	57.12	228.48	L	Y	
55 REAR BLIND SPOT COLLISION WARNING UNIT <i>x</i>	1.00	1,879.61	375.92	1,503.69	L	Y	
56 REAR BUMPER CLIP SET <i>re</i>	1.00	85.00	0.00	85.00	S	Y	<i>30</i>
57 REAR BUMPER PROTECTOR <i>cm</i>	1.00	160.00	0.00	160.00	S	Y	<i>50</i>
58 REAR BUMPER UNDER COVER CLIP SET <i>re</i>	1.00	80.00	0.00	80.00	S	Y	<i>40</i>
59 REAR BUMPER LOWER CENTER MOULDING CLIP <i>re</i>	1.00	55.00	0.00	55.00	S	Y	<i>30</i>
60 REAR BUMPER CENTER MOULDING CLIP <i>re</i>	1.00	60.00	0.00	60.00	S	Y	<i>30</i>
61 REAR REVERSE SENSOR SET <i>re</i>	2.00	600.00	0.00	600.00 <i>200</i>	S	Y	<i>40 200</i>
62 REAR LICENCE PLATE NUMBER WITH FRAME <i>cm</i>	1.00	150.00	0.00	150.00	S	Y	<i>35</i>
63 TAILLAMP GUIDE CLIP SET <i>re</i>	1.00	55.00	0.00	55.00	S	Y	<i>20</i>
64 REAR END PANEL SEALANT <i>re</i>	2.00	180.00	0.00	180.00	S	Y	<i>40</i>
65 REAR FLOOR PAN SEALANT <i>x re</i>	2.00	180.00	0.00	180.00	S	Y	<i>x</i>
66 REAR SPOILER CLIP AND PAD SET <i>re</i>	1.00	60.00	0.00	60.00	S	Y	<i>30</i>
67 REAR WINDSCREEN PRIMER <i>re</i>	1.00	120.00	0.00	120.00	S	Y	<i>60</i>
68 REAR WINDSCREEN SEALANT <i>re</i>	3.00	300.00	0.00	300.00	S	Y	<i>100</i>
69 REAR WINDSCREEN GLASS PAD SET <i>re</i>	1.00	50.00	0.00	50.00	S	Y	<i>30</i>
70 REAR WINDSCREEN GLASS STOPPER SET <i>re</i>	1.00	55.00	0.00	55.00	S	Y	<i>30</i>
71 REAR END PANEL TRIM BOARD CLIP <i>re</i>	1.00	60.00	0.00	60.00	S	Y	<i>30</i>
72 REAR BOOT TRIM BOARD CLIP SET <i>re</i>	1.00	75.00	0.00	75.00	S	Y	<i>30</i>
73 REAR TAILGATE "6552-1111" STICKER <i>re</i>	1.00	150.00	0.00	150.00	S	Y	<i>80</i>
74 REAR TAILGATE "BOOK NOW" STICKER <i>re</i>	1.00	150.00	0.00	150.00	S	Y	<i>60</i>
75 REAR TAILGATE "COMFORT DELGRO" STICKER <i>re</i>	1.00	150.00	0.00	150.00	S	Y	<i>80</i>
76 FENDER LINER CLIP SET <i>x</i>	1.00	75.00	0.00	75.00	S	Y	<i>x</i>
77 REAR LUGGAGE SIDE TRIM CLIP <i>re</i>	1.00	65.00	0.00	65.00	S	Y	<i>30</i>
TOTAL:		27,004.91	,818.00	22,186.91			

TOTAL PARTS & LABOUR :

34,324.91

4,818.00

29,506.91

EXCESS/LOADING:\$ \$ 0.00

No. Of Day:

*9 days P/P*RE-SURVEY: BEFORE AFTER PAINTINGPART-BY-PART OR LUMP SUM: \$ \$DATE OF SURVEY: *14 / 06 / 21 @ 1520*

SURVEYED BY:

RASUL

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED BY Reparer

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	11/06/2021 15:21 (SGT)
Date of Accident	11/06/2021 09:30 (SGT)
Exact Location of Accident	Ubi Ave 2, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB2889J
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CITYCAB PTE LTD
Company Reg No	1XXXXX839G
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-91464180
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419140
Cover Note Number	-

DRIVER

Name of Driver	ADAM TAN HOCK LIM
NRIC No	SXXXX129I

Date Of Birth	15/04/1967
Occupation	Outdoor
Date Of Driving Pass	04/02/1989
Driving experience	32 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91464180
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 346 BUKIT BATOK STREET 34 #04-222
Address complement	-
Postcode	650346
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bishan Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005529999
Alt. Police Station Phone No	(Fax) +65-65561905
Police Station Address	20 Bishan Street 23 Singapore 579757
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH1110T
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category	Commercial vehicle
Name of Driver	NG CHEOW HUA
NRIC No	SXXXX949I
Contact Number	(Phone) +65-98232961
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ADAM TAN HOCK LIM
Address	BLK 346 BUKIT BATOK STREET 34 #04-222
Address Complement	-
Post Code	650346
Approximate Age Years Old	54
Injuries Sustained	BACK PAIN. GIVEN 5 DAYS MC.
Injured person in which vehicle?	SHB2889J
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A	S17B2889J
B	GBH1110T

PRYALCER KOND

UNBURNED

Describe Circumstances of the Accident

REFER TO POLICE REPORT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

11 / 06 / 21 / 1430 hrs

Witnessed by Reporting Centre
Personnel



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	839G
Vehicle No.:	SHB2889J
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jun 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Yellow
Manufacturing Year:	2019
Engine No.:	G4LEKU391114
Chassis No.:	KMHC851CVLU184582
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,755.00
Original Registration Date:	30 Oct 2020
First Registration Date:	30 Oct 2020
Transfer Count:	0
Actual ARF Paid:	\$13,057.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2028
PARF Rebate Amount:	\$9,792.00
COE Expiry Date:	29 Oct 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$28,160.00
COE Rebate Amount:	\$25,945.00
Total Rebate Amount:	\$35,737.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Jun 2021

OK