

HWA SENG SPRAY PAINTING PTE LD

160 Sin Ming Drive

#05-11 Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO.: 202017045G)

TEL : 64533100

62669932

Date of Accident :

10/06/2021

QD Chian

Policy No : 7210006124

NOT Notarized

Running B6 paint 4 days

84062-30

ESTIMATE REPAIR COSTS TO TOYOTA HIACE REG. NO. : GBF 7468 H

\$

1pc	Bonnet		B1	756.60	✓
1pc	Logo Emblem		na	66.20	✓
2pcs	Bonnet Hinges	(\$48.90/pc)	n	97.80	x
1pc	Front Grille : Top		sn	191.50	x
1pc	Front Grille : Lower		nd/bt	330.80	✓
1pc	Front Grille : Inner	432	my cm	491.10	✓
1pc	Front Bumper		Bu/nd	487.10	✓
2pcs	Headlamp	0848.70 (\$948.70/pc)	my cm	1897.40	✓
1pc	Front Bumper Reinforcement	272	B1	304.40	✓
1pc	Support Panel		n	283.10	x
1pc	Bonnet Lock		n	77.50	x
1pc	Air Con Condenser		sn	1216.10	x
1pc	Front Bumper Towing Cover		sn	26.20	x
1pc	Front Bumper Lower Grille		cm	154.30	✓
1pc	Side Fog lamp Cover		sn	62.40	x
1pc	Front Bumper Retainer		sn	193.10	x
1pc	Front Bumper Brace Panel		n	56.70	x

6692.30

Less : 25%

1673.08

5019.22

LABOUR & MISC CHARGES

Panel Knocking	500.00	400f
Spray Painting	500.00	450f
Wire Checking	50.00	20f
Vacuum & Top Up Air Con Gas	NN 150.00	x
Number Plate with Casing	nd 70.00	45SN

TOTAL 6289.22

HWA SENG SPRAY PAINTING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: