

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 11-Jun-21

INSURANCE: MSIG

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA9479T

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>RT</i>	1	\$1,126.60	\$1,126.60
REAR TRUNK LID LOCK <i>SL</i>	1	\$457.90	\$457.90
REAR TRUNK LID COVER TRIM BOARD <i>HL</i>	1	\$254.40	\$254.40
Boot Lid Trimboard, Centre <i>HL</i>	1	\$159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH) <i>HL</i>	1	\$92.50	\$ 92.50
Boot Lid Trimboard REAR <i>HL</i>	1	\$124.80	\$ 124.80
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>broken</i>	1	\$896.30	\$896.30
REAR TRUNK LID LOGO (PRIUS) <i>HCC</i>	1	\$60.80	\$60.80
REAR TRUNK LID LOGO (HYBRID) <i>HCC</i>	1	\$52.40	\$52.40
REAR TRUNK LID LOGO (TOYOTA STAR) <i>HCC</i>	1	\$52.90	\$52.90
REAR BUMPER <i>Dent / crack</i>	1	\$458.60	\$458.60
REAR BUMPER RE-INFORCEMENT <i>RT</i>	1	\$318.80	\$318.80
REAR BUMPER LOWER COVER <i>distorted / end</i>	1	\$552.60	\$552.60
REAR BUMPER SIDE RETAINER <i>SL</i>	1	\$112.70	\$112.70
REAR BUMPER TOWING COVER <i>distorted</i>	1	\$82.70	\$82.70
REAR BUMPER CLIPS <i>HCC</i>	1	\$22.00	\$22.00
REAR BUMPER SIDE CLIP <i>HL</i>	1	\$25.00	\$25.00
REAR BUMPER UPPER STOPPER (LH) <i>SL</i>	1	\$76.40	\$76.40
SEAL, REAR BUMPER SIDE, LH <i>RT RH distorted</i>	1	\$148.40	\$148.40
REAR BUMPER UNDER SIDE COVER (LH) <i>RT HL</i>	1	\$232.00	\$232.00
ARM SUB-ASSY, REAR BUMPER, (LH) <i>RT HL</i>	1	\$139.60	\$139.60
REAR BUMPER REVERSE SENSOR <i>Dent</i>	1	\$235.70	\$235.70
TAIL LAMP ASSY (UPPER) <i>many crack RH</i>	1	\$557.90	\$557.90
TAIL LAMP ASSY (LOWER) <i>crack RH</i>	1	\$548.40	\$548.40
TAIL LAMP QUARTER PANEL <i>Dent</i>	1	\$216.00	\$216.00
TAIL LAMP SIDE COVER <i>SL</i>	1	\$256.00	\$256.00
REAR END PANEL <i>Dent</i>	1	\$602.10	\$602.10
REAR END PANEL GARNISH <i>HL</i>	1	\$165.80	\$165.80
REAR WIRING ASSY <i>HL</i>	1	\$582.40	\$582.40
REAR SPARE TYRE PANEL <i>HL</i>	1	\$667.70	\$667.70
REAR FIBER TOOL BOX TRIM (LH) <i>HL</i>	1	\$598.00	\$598.00
REAR FIBER TOOL BOX CENTER <i>HL</i>	1	\$186.20	\$186.20
SPARE TYRE LOCK NUT <i>HL</i>	1	\$88.40	\$88.40
SPARE TYRE LOCK NUT BRACKET <i>HL</i>	1	\$113.50	\$113.50
SPARE TYRE SIDE PANEL (LH) <i>HL</i>	1	\$287.30	\$287.30
REAR EXHAUST PIPE RH <i>HL</i>	1	\$1,163.40	\$1,163.40
REAR EXHAUST PIPE HANGER <i>HL</i>	1	\$40.70	\$40.70
REAR EXHAUST PIPE INSULATOR <i>HL</i>	1	\$314.60	\$314.60
REAR FENDER, RH <i>Dent</i>	1	\$836.70	\$836.70
REAR FENDER SHIELD (LH) <i>HL</i>	1	\$174.20	\$174.20
REAR FENDER AIR DUCT <i>distorted</i>	1	\$165.10	\$165.10

135.70 SH

SUB TOTAL					\$13,247.10
LESS 20% 25%					\$2,649.42
DISCOUNTED TOTAL					\$10,597.68
REAR TRUNK LOWER W/S MOULDING Hec	SN	1	\$180.00	\$180.00	✓
REAR LOWER W/S SEALANT Hec	SN	1	\$46.00	\$46.00	✓
REAR WINDSCREEN MOULDING Hec	SN	1	\$160.00	\$160.00	✓
REAR WINDSCREEN SEALANT Hec	SN	1	\$46.00	\$46.00	✓
REAR BUMPER ADVERTISEMENT Hec	SN	1	\$100.00	\$100.00	✓
REAR FENDER ADVERTISEMENT LOGO (LH) Hec	SN	1	\$100.00	\$100.00	✓
SUB TOTAL					\$632.00
Labour Charge					
Panel Beating		1	\$1,400.00	\$1,400.00	700/-
Spray Painting Charge		1	\$1,200.00	\$1,200.00	700/-
Wiring Charge		1	\$100.00	\$100.00	30/-
Tuff Kote		1	\$100.00	\$100.00	40/-
Towing Charge		1	\$80.00	\$80.00	40/-
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass		2	\$120.00	\$240.00	80/-
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	40/-
Remove/Refix Fuel Tank		1	\$80.00	\$80.00	40/-
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	40/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	40/-
TOTAL LABOUR					\$4,100.00
ESTIMATE TOTAL					\$15,329.68
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

6698.30

5023.72

717.70

50/-

1670.00

14/06/2021 @ 1700hrs

NA Ardu

2/3 hrs 6 days

1 N/A

2kk Auto

7/P 7411.42

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: