

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

A/G

Name : Lai Ban Chow

Accident Date : 30-May-21

Vehicle No : JNR5466

Vehicle Model : Yamaha 135LC

Accident involving GBC3257S and JNR5466 on 30 May 2021

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy Dis —	520 \$ 640.00 ✓
1	Front wheel rim moped —	250 \$ 380.00 ✓
1	Fork under bracket Bel —	\$ 185.00 ✓
1	Front rim shaft Bel —	\$ 45.00 ✓
1	Front rim bearing Dayes —	\$ 38.00 ✓
1	Front brake disc Bel —	105 \$ 165.00 ✓
1	Front fairing inner cover CNA —	\$ 175.00 ✓
1	Handle bar 1 1 X	\$ 88.00 X
2	Handle bar ends 1 1 X	\$ 78.00 X
1	Hand grip (1 set) 1 1 X	\$ 75.00 X
1	Handle bar inner bracket 1 X	\$ 88.00 X
2	Side mirrors 0/5 cur 1/2 C	48 \$ 110.00 1/2 C
1	Brake lever 0/5 SCA ✓	35 \$ 42.00 ✓
2	Front signals CNA —	\$ 160.00 ✓
1	Front signal lower garnish CNA —	\$ 105.00 ✓
1	Headlamp CNA —	150 \$ 225.00 ✓
1	Fairing assy (1 set) 320 —	450 \$ 525.00 ✓
1	Front footrest bracket Bel —	\$ 65.00 ✓
2	Front footrest rubbers 0/5 1/2 1/2 C	30 \$ 70.00 1/2 C
1	Brake pedal 2 X	\$ 42.00 X
2	Rear footrests 0/5 cur 1/2 C	30 \$ 80.00 1/2 C
2	Rear footrest brackets 0/5 CNA 1/2 C	68 \$ 156.00 1/2 C
1	Exhaust assy 2 X	\$ 585.00 X
1	Exhaust protector - Chrome Bel —	\$ 75.00 ✓
1	Exhaust protector - Black Bel —	\$ 55.00 ✓
1	Radiator CNA 1/2 1/2 —	350 \$ 485.00 ✓
1	Spare tank 2 1 X	\$ 105.00 X
1	Basket 1 1 X	\$ 85.00 X
		\$ 4,927.00
	Less 10%	\$ 492.70
		\$ 4,434.30

Not full

2/5

15/6/21

maybe 7000 10000
5 days.

2/5 1300

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Lai Ban Chow

Accident Date : 30-May-21

Vehicle No : JNR5466

Vehicle Model : Yamaha 135LC

Accident involving GBC3257S and JNR5466 on 30 May 2021

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	1111 10	\$	28.00	10
2	Fork oils	11X	\$	30.00	X
2	Fork oil seals	11X	\$	56.00	X
1	Steering cone (1 set)	100 50	\$	90.00	50
1	Front tyre	SUCX	\$	280.00	X
			\$	484.00	


S/No. Labour

1	To provide towing service (LOD)	\$	35.00	✓
2	To check wiring and reset headlamp focusing	\$	11 80.00	X
3	To provide labour	\$	300 420.00	
4	To repair body frame	\$	200 380.00	
		\$	915.00	

Grand Total

\$ 5,833.30

Singapore Dollars: Five Thousand Eight Hundred Thirty-Three and Cents: Thirty only


EROFIA MOTOR TRADING PTE LTD

3267.1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary demand must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: