



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301978

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 30/03/2023
Reference CC6/CTI21006664/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNA 433M
Insured Veh. SJJ 7116H
Claim No. SNM21D203377/C02
Policy No.
Accident Date 13/06/2021
Inspection Date 14/06/2021

Description	Total
Survey Inspection	280.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	280.00
GST (8%)	22.40
Grand Total	302.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21006664/Upa3q2 Date: 30/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJJ 7116H	Veh. Inspected	SNA 433M	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM21D203377/C02	Excess (\$)	0.00	
Assign From		Assign Date	14/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 325I (A)	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WBAWL12060PD76553	Colour	BLACK	
Odometer	92533 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	PIRELLI	6 mm	
L/H Front Tyre	225/40 R18	PIRELLI	6 mm	
R/H Rear Tyre	255/40 R18	PIRELLI	6 mm	
L/H Rear Tyre	255/40 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2021	Inspection Date	14/06/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 433M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT/ BUCKLED	2,432.62	1,649.50
1	BONNET LOGO	CRACKED	105.00	85.50
1	BONNET INSULATOR	NOT NECESSARY	248.22	-
1	SET BONNET INSULATOR CLIPS	NOT NECESSARY	50.00	-
1	BONNET LOCK LEVEL	BENT	169.20	166.20
1	BONNET LOCK CATCH	SERVICEABLE	188.00	-
2	BONNET HINGES @\$85.00	NOT NECESSARY	170.00	-
2	FRONT GRILLE CHROMES @\$195.00	CRACKED	390.00	360.00
2	FRONT GRILLE BASES @\$180.00	CRACKED	360.00	332.00
1	FRONT BUMPER	DENTED	1,651.23	1,122.35
1	FRONT BUMPER BEAM	TO REPAIR SEE LABOUR	788.21	-
1	FRONT BUMPER LOWER CENTRE GRILLE	NOT NECESSARY	148.20	-
1	FRONT BUMPER TOP STRIP	NECESSARY	68.00	68.00
2	FRONT BUMPER FOG LAMPS @\$490.00	NOT NECESSARY	980.00	-
2	FRONT BUMPER SIDE RETAINERS @\$60.00	NOT NECESSARY	120.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
2	HEADLAMPS @\$2822.00	CRACKED	5,644.00	4,847.60
1	HEADLAMP LIGHT ECU (SHORTED)	NOT CONSISTENT WITH THE IMPACT	898.50	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	845.21	-
1	FRONT BRACE PANEL	BENT	166.00	166.00
1	FRONT AIR INTAKE NOSE GARNISH	DEFORMED / TORN	232.45	194.30
1	FRONT LOWER INNER GARNISH	CRACKED	215.60	162.30
2	FRONT FENDERS @\$855.00	TO REPAIR SEE LABOUR	1,710.00	-
1	AIR CON CONDENSER	NOT NECESSARY	1,185.00	-
1	RADIATOR	NOT NECESSARY	1,220.00	-
	LESS 5% DISCOUNT		-	-460.19
			20,035.44	8,743.56



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER LICENCE PLATE (SN)	BROKEN	50.00	40.00
1	BOL RADIATOR COOLANT (SN)	NOT NECESSARY	50.00	-
			100.00	40.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO REFILL AIR CON GAS .	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO RESET & REPROGRAMME SYSTEM.		180.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS .INCLUSIVE OF THE REPAIR OF FRONT BUMPER BEAM ,FRONT SUPPORT PANEL AND FRONT FENDERS.		880.00	520.00
	TO PUTTY & SPRAY PAINTING.		1,280.00	600.00
			2,590.00	1,220.00
	GRAND TOTAL		22,725.44	10,003.56
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,000.00

Report Ref No. CC6/CTI21006664/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNA 433M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNA 433M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

