

ASSIGNMENT

From:

Date:

Veh No:

SLU73404

Yr Regn:

12/12/17

Estimated Cost:

Type: M.Cdr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

(A)

To Inspect Vehicle No:

SLU73404

Make:

Toyota Sienta

c.c 1496

at Workshop m/s

hup notu

Colour

Slack

A/C: Insured / Std / NI / NA

of

Sp. Reading

76781

T/Radio: Insured / Std / NI / NA

Insured:

GBH1444B

Eng/No:

Policy No.

C/No:

MHF228H 3500045163

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 195/50 R16

R:

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

\$69k

Front

Rear

IDAC Accident Rport:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

5

days

Res.: Yes or No

D.O.A.

100%

3 Val.: Yes or No

9261

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 RR.

The U/C / Chassis frame / Body Structure affected due to collision.

Date:

Person Contacted:

Vehicle: IN / OUT

9800

Date / Time

Action / Instruction

27/11/17 8:41:09

No second hand parts.

27/11/17 confirmed 7/17 \$6397.45 with David

Date/Time, File Pass to?

: Preli. Report

Days Of Repair:

1)

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

: Site Insp (\$

) ___ S + RS ___ SI

: Interview (\$

) Photos

: Tech. Invs (\$

) Others

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmoto@gmail.com Reg. No. 37809/00W

Our Ref: TF3027/06/21

Your Ref: *Not Authorized*
Lee
14/6/21
5 days
14/6/21

LKK Auto Consultants (Singapore) notify the Repairer of the following:

- To ensure the vehicle is being repaired
- To display damaged parts during resurvey
- Print prices are subject to confirmation
- Third party survey is on a "without prejudice" basis

is subject to final approval from Insurance Company

Date: **14th JUN 2021**

Acknowledged by Repairer
Signature:
Date:

MR LEE TUCK MENG
1, Fernvale Close,
#07-04, Lush Acres
Singapore 797485

Estimate cost of repair to TOYOTA SIENNA 1.5 (A) Elegance M/B - SLU 7340 U

1 pc front o/s fender	<i>Bodily DD</i>	\$ 713.20
1 pc front o/s fender inner shield	<i>Dis/ton</i>	216.70
8 pcs front o/s fender inner shield clips	<i>all</i>	34.40
10 pcs front bonnet insulator clips	<i>all</i>	48.00 X
1 pc o/s head lamp assy	<i>3/20</i>	24.00 X
1 pc o/s head lamp bracket	<i>Dis</i>	599.60
1 pc front bumper		68.80
16 pcs front bumper top & low clips	<i>all</i>	383.90
1 pc front bumper reinforcement	<i>3/20</i>	193.30 X
1 pc front bumper lower rubber	<i>all</i>	35.40 X
8 pcs front bumper lower rubber clips	<i>all</i>	65.90
1 pc front bumper top rubber	<i>sch</i>	25.80 X
6 pcs front bumper top rubber clips	<i>all</i>	458.10
1 pc front bumper o/s fog lamp assy	<i>CR</i>	108.50
1 pc front bumper o/s fog lamp garnish	<i>Dis</i>	73.90
1 pc front bumper o/s side retainer	<i>CR</i>	54.90
1 pc front bumper o/s top retainer	<i>3/20</i>	689.60
1 pc front grille	<i>Dis</i>	80.20 X
1 pc front grille logo	<i>all</i>	154.20 X
1 pc front grille moulding	<i>all</i>	25.80 X
6 pcs front grille clips	<i>all</i>	141.40 X
1 pc washer tank	<i>all</i>	213.50 X
1 pc front o/s top panel	<i>all</i>	150.30 X
1 pc o/s head lamp panel	<i>all</i>	

\$ 7,991.30
Less 25% \$ 1,997.83
\$ 5,993.47

- To wiring check up & adjust headlight alignment. 50.00 *20*
- To check & adjust front wheel alignment & balancing. 120.00 *60*
- To respray Tuff-Kote on all affected accident parts. *all* 80.00 X
- Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts, to 950.00 *550*
- To putty & respray painting on all affected accident parts. 1,450.00 *880*

HUP MOTOR TRADING & SERVICE

\$ 8,643.47
=====

Dollars : Eight Thousand Six Hundred Forty Three And Cents Forty Seven Only.

P= 58166
252
4887-4
6797-1