



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21006667/R1qf3e2 Date: 24/11/2021 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	XE 725G
	Policy No.	Z21VC05006850	Coverage (\$)	0.00
	Claim No.	21/21/21/VC05/024623	Excess (\$)	1,500.00
	Assign From	KENNY LIM	Assign Date	14/06/2021
2. Vehicle Particulars & Condition				
	Make & Model	SCANIA P440CB 6X4MHZ	c.c	12742
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	YS2P6X40005358161	Colour	WHITE
	Odometer	78837 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	315/80 R22.5	GITI	8 mm
	L/H Front Tyre	315/80 R22.5	GITI	8 mm
	R/H Rear Tyre	315/80 R22.5 (D)	GITI	8/8 mm
	L/H Rear Tyre	315/80 R22.5 (D)	GITI	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/06/2021	Inspection Date	15/06/2021
	Survey held at	located at 10, Penjuru Close		
	Repairer	KAN FOOK SING MOTOR WORKSHOP		
5a. Remarks				
	A) THE MARKET VALUE IS S\$102,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	