

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110  
Mobile : 9855 6879 Email : automaxsurvey@gmail.com  
Registration No. 53110062J

Billing To: Ong Bock Hay  
c/o Eng Soon Painting SVC  
Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677969

Invoice no.: TP21020035

Date: 07 MAY 2021

Vehicle no: SLL5550R

Model : HONDA ODYSSEY 2.4

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 01 March 2021 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 600.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
TOTAL :		\$ 600.00

## Notes :

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.

Official Stamp



# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110  
Mobile : 9855 6879 Email : automaxsurvey@gmail.com  
Registration No. 53110062J

Report Ref : TP21020035

Date: 07 MAY 2021

**Ong Bock Hay**  
**c/o Eng Soon Painting SVC**  
**Blk 4 Yew Tee Ind Est 393 - J**  
**Woodlands Road**  
**Singapore 677969**

## THIRD PARTY SURVEY ACCIDENT OCCURED ON 19 FEB 2021

Workshop Name and Address

Eng Soon Painting SVC  
Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677969

As per your instruction dated 01 March 2021  
We have carried out a physical inspection on the said  
We enclosed herewith our report and findings as follows:

with regard to the above matter.  
SLL5550R

### 1. VEHICLE PARTICULARS

Registration No : SLL5550R  
Model : HONDA ODYSSEY 2.4  
Year / Capacity : Mar 2017 / 2398 cc  
Chassis No : JHMRC1890GC209959

Engine No : K24W72013982  
Mileage : 119 618 km  
Colour : Metallic White

### 2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	215/55/R17	Toyo	9.00 mm	Sport
REAR O/S :	215/55/R17	Toyo	9.00 mm	Sport
FRONT N/S :	215/55/R17	Toyo	9.00 mm	Sport
REAR N/S :	215/55/R17	Toyo	9.00 mm	Sport

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

## 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SLL5550R

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Rear bumper	bend/deformed	\$ 1,648.50	\$ 1,648.50
1 pc	Rear bumper side retainer	distorted	\$ 65.00	\$ 65.00
1 pc	Rear bumper side attachment	bent/distorted	\$ 45.00	\$ 45.00
10 pcs	Rear bumper clips	necessary	\$ 80.00	\$ 80.00
1 pc	Rear fender	bend/distorted	\$ 1,291.50	\$ 1,291.50
1 pc	Rear door assy	dent - repair	\$ 1,450.00	\$ -
1 pc	Rear door weatherstrip	wrapped/deformed	\$ 225.00	\$ 225.00
1 pc	Rear wheel bearing hup	bent/distorted	\$ 625.00	\$ 625.00
1 pc	Tail lamp assy	necessary	\$ 425.00	\$ 425.00
1 pc	Tail lamp sealant	necessary	\$ 55.00	\$ 55.00
2 pcs	Tail lamp clips	necessary	\$ 40.00	\$ 40.00
Parts Sub-Total			\$ 5,950.00	\$ 4,500.00
Discount 20.00%			\$ 1,190.00	\$ 900.00
			\$ 4,760.00	\$ 3,600.00

Vehicle Number : SLL5550R

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 set	Rear bumper parking sensor	electronically shocked	\$ 280.00	\$ 250.00
1 pc	Rear bumper parking sensor wire	open circuit	\$ 180.00	\$ 180.00
1 pc	Rim assembly (sport)	grazed/distorted	\$ 480.00	\$ 480.00
1 pc	Tyre assembly	grazed/deformed	\$ 350.00	\$ 280.00
Special Nett Sub-Total			\$ 1,290.00	\$ 1,190.00
Spare Parts Total			\$ 6,050.00	\$ 4,790.00

## LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 6,050.00	\$ 4,790.00
1	To tuff coat affected areas	\$ 180.00	\$ 150.00
2	To remove and refix interior upholstery	\$ 180.00	\$ 150.00
3	To respray affected areas	\$ 1,400.00	\$ 1,200.00
4	To renew damaged parts, straighten and repair rear fender inner, front and rear chassis member and aligned all parts	\$ 1,600.00	\$ 1,400.00
5	To check and reconnect snap wiring	\$ 180.00	\$ 150.00
6	To remove and replace reverse sensor & camera	\$ 180.00	\$ 150.00
7	To remove and replace undercarriage	\$ 180.00	\$ 150.00
8	To remove & transfer rear door mechanism	\$ 180.00	\$ 150.00
9	To check and adjust computer wheel alignment	\$ 180.00	\$ 150.00
	Total	\$ 10,310.00	\$ 8,440.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 7,200.00

  
Fong Kok Heng  
Qualified Appraiser

