

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

GJ11306125

ESTIMATE OF REPAIR

Veh# : SJK7136U

TE ALG.

Model: HONDA AIRWAVE

Accident Date : 11/6/2021

(30/10/2008)-(29/10/2023)

Location : CAUSEWAY POINT BASEMENT CARPARK

Xiao Tong

3P: SFC9393U (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Disbld</i>	726.70	✓	
2	10 pcs	Front bumper clips <i>new</i>		30.00	✓
3	1pc	Front bumper lower lip <i>could</i>		600.00	<i>sw</i>
4	1 pc	Front bumper n/s retainer <i>new</i>	86.70	✓	
5	1 pc	Front bumper grille (Lower) <i>new</i>	496.60	x	
6	1 pc	Front bumper n/s fog lamp <i>new</i>	316.70	x	
7	1 pc	Front grille <i>could</i>	436.70	✓	
8	6 pcs	Front grille clips <i>new</i>		18.00	✓
9	1 pc	Front n/s head-lamp <i>could</i>	896.80	✓	
10	1set	Front head lamp chrome <i>new</i>		200.00	x
11	1 pc	Front o/s head lamp retainer <i>new</i>	65.70	x	
12	1 pc	Front n/s fender <i>new</i>	796.80	x	
		Sub-Total:	3,822.70	848.00	0.00
			20%	0%	0%
		After Less %:	3,058.16	848.00	0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.		600.00 <i>400</i>	
2		To spray painting.		450.00 <i>400</i>	
3		To check wiring.		30.00	✓
		Sub-Total:		1,080.00	
		Total:		4,986.16	
		After Less 20%:		3,988.93	

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

List: 214690

Labour: 830

Admin L

Am 20%: 1717.52

Label: 3095.52 n/s 14/06/21.

S/N: 548

L/S: 2450

04 Prys.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJK7136U ESTIMATEPg1

8778 1999
24 hr accident call

Mobil 1

