



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :		Page :	1/2
Our Ref :	TP0048/06/21	Date :	14/06/2021

THIRD PARTY CLAIM

M/S : TAN JIUNIN HOW
 BLK 552 WOODLANDS DRIVE 44
 #12-26
 SINGAPORE 730552

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLC5080C - VOLKSWAGON SPORTSVAN
 INSURED : TAN JIUNIN HOW ENGINE# :
 DATE OF ACCIDENT : 11/06/2021 CHASSIS# :
 POLICY NO : MP317614

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
<u>Replacement of Parts</u>				
1 rear windscreen rubber moulding	1@	226.00	226.00	226.00
2 rear boot	1@	1771.00	1771.00	1,771.00
3 rear boot center logo with lock handle	1@	110.00	110.00	110.00
4 rear number plate lamp L&R	2@	80.00	80.00	160.00
5 rear boot 230TSI emblem	1@	88.00	88.00	88.00
6 rear lamp assy RH	1@	277.00	277.00	277.00
7 rear bumper	1@	1056.00	1056.00	1,056.00
8 rear bumper parking sensor	3@	199.00	199.00	597.00
9 rear bumper lower spoiler	1@	388.00	388.00	388.00
10 rear bumper top support fibre enforcement	1@	80.00	80.00	80.00
11 rear bumper reinforcement	1@	528.00	528.00	528.00
12 rear bumper towing hook cover	1@	35.00	35.00	35.00
13 rear bumper reflector lamp	1@	75.00	75.00	75.00
14 rear bumper side retainer L&R	2@	60.00	60.00	120.00
15 rear boot rubber	1@	299.00	299.00	299.00
16 rear boot lamp	1@	244.00	244.00	244.00
17 rear lamp center panel	1@	627.00	627.00	627.00
18 rear lamp panel inner center garnish	1@	173.00	173.00	173.00
				6,854.00
Less 10%				-685.40
Total Material				\$6,168.60
<u>Special Nett Items</u>				
19 rear windscreen sealant	1@	40.00	40.00	40.00
20 rear number plate w/casing	1@	45.00	45.00	45.00
				85.00
Total S/Nett				\$85.00



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :

Page

: 2/2

Our Ref : TP0048/06/21

Date

: 14/06/2021

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
<u>Labour & Misc</u>				
1 Remove & install rear windscreen.				150.00
2 Remove & install rear carpet.				100.00
3 Reset parking sensor.				120.00
4 Check wiring system.				25.00
5 Remove & install r/boot, r/lamp, r/bumper, cut out & renew r/lamp center panel, knock spare tyre panel and restraigthen bofy & Chassis.				1,100.00
6 Spray painting.				1,000.00
				<u>2,495.00</u>
Total Labour				<u>\$2,495.00</u>
Nett Total Before Gst				<u>\$8,748.60</u>

Your faithfully

NPH AUTO SERVICE
(Manager)