



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Your Ref :
 Our Ref : TP0048/06/21
 Page : 1/2
 Date : 14/06/2021

THIRD PARTY CLAIM
 M/S : TAN JIUNIN HOW
 BLK 552 WOODLANDS DRIVE 44
 #12-26
 SINGAPORE 730552

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLC5080C - VOLKSWAGON SPORTSVAN
 INSURED : TAN JIUNIN HOW
 DATE OF ACCIDENT : 11/06/2021
 POLICY NO : MP317614

ENGINE# :
 CHASSIS# : 2497614

*rest of car
 14/6/21
 4/5/21
 H days.*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total	
		\$	\$	\$	
Replacement of Parts					
1 rear windscreen rubber moulding	1@	226.00	226.00	226.00	✓
2 rear boot	1@	1771.00	1771.00	1,771.00	✓
3 rear boot center logo with lock handle	1@	110.00	110.00	110.00	✓
4 rear number plate lamp L&R	2@	80.00	80.00	160.00	X
5 rear boot 230TSI emblem	1@	88.00	88.00	88.00	✓
6 rear lamp assy RH	1@	277.00	277.00	277.00	✓
7 rear bumper	1@	1056.00	1056.00	1,056.00	✓
8 rear bumper parking sensor	3@	199.00	199.00	597.00	✓
9 rear bumper lower spoiler	1@	388.00	388.00	388.00	✓
10 rear bumper top support fibre enforcement	1@	80.00	80.00	80.00	✓
11 rear bumper reinforcement	1@	528.00	528.00	528.00	✓
12 rear bumper towing hook cover	1@	35.00	35.00	35.00	X
13 rear bumper reflector lamp	1@	75.00	75.00	75.00	X
14 rear bumper side retainer L&R	2@	60.00	60.00	120.00	X
15 rear boot rubber	1@	299.00	299.00	299.00	✓
16 rear boot lamp	1@	244.00	244.00	244.00	✓
17 rear lamp center panel	1@	627.00	627.00	627.00	X
18 rear lamp panel inner center garnish	1@	173.00	173.00	173.00	X
				6,854.00	
				-685.40	
Less 10%					
Total Material				\$6,168.60	
Special Nett Items					
19 rear windscreen sealant	1@	40.00	40.00	40.00	✓
20 rear number plate w/casing	1@	45.00	45.00	45.00	40
				85.00	
Total S/Nett				\$85.00	



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Your Ref :

Page

: 2/2

Our Ref : TP0048/06/21

Date

: 14/06/2021

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Labour & Misc				
1 Remove & install rear windscreen.			120	150.00
2 Remove & install rear carpet.			80	100.00
3 Reset parking sensor.			50	120.00
4 Check wiring system.			20	25.00
5 Remove & install r/boot, r/lamp, r/bumper, cut out & renew r/lamp center panel, knock spare tyre panel and restraighthen bofy & Chassis.			700	1,100.00
6 Spray painting.			850	1,000.00
				2,495.00

Total Labour

\$2,495.00

Nett Total Before Gst

\$8,748.60

Your faithfully

NPH AUTO SERVICE
(Manager)

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: