



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mr Moey Weng Foong 42 East Coast Avenue Singapore 459247 Mobile: 98764830			
			Document No. 39011887					
			Document Date 10/07/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	AGH30R	PFXLK E2	26/07/2017	SGM0900B	55907	21019	67/DS/SGM0900B	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTNGF3DH908010991		2ARH957429	60	Sam San Joi	14/06/2021	13.01	10/07/2021 10.12	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SHB1745Y ACC DATE:11/06/2021 DRIVE IN:14/06/2021 DATE-IN:21/06/2021 DATE SURVEY:21/06/2021 NO OF REPAIR DAYS:5 DAYS BY:ADRIAN(LKK)						30.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM			*			122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME			BP08			180.00
4	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS			*			1440.00
5	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS			*			2065.00
6	1	T52119-58947	COVER, FR BUMPER		1.00	667.60		667.60
7	2	T52115-58060	SUPPORT, FR BUMPER		1.00	99.20		99.20
8	3	S52161-0K040	PIECE, RR BUMPER		10.00	4.10		41.00
9	4	T53801-58050	FENDER SUB-ASSY, FR		1.00	1259.40		1259.40
10	5	T81145-58350	UNIT, HEADLAMP		1.00	3835.60		3835.60
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 9,740.20		
		Please acknowledge receipt of vehicle 		Parts	5,902.80	GST 7.00% 681.81		
				Labour	3,837.40			
				Sublet	0.00	Less 0.00		
				Lubrication/Fluid	0.00			
				Others	0.00	Amount Due 10,422.01		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept				S1000005 / ICFIC1		Mr Moey Weng Foong 42 East Coast Avenue Singapore 459247 Mobile: 98764830			
				Document No. 39011887					
				Document Date 10/07/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	AGH30R	PFXLK E2	26/07/2017	SGM0900B	55907	21019	67/DS/SGM0900B		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTNGF3DH908010991		2ARH957429	60	Sam San Joi	14/06/2021	13.01	10/07/2021	10.12	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SHB1745Y ACC DATE:11/06/2021 DRIVE IN:14/06/2021 DATE-IN:21/06/2021 DATE SURVEY:21/06/2021 NO OF REPAIR DAYS:5 DAYS BY:ADRIAN(LKK)							30.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				*			122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				BP08			180.00
4	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS				*			1440.00
5	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS				*			2065.00
6	1	T52119-58947	COVER, FR BUMPER		1.00	667.60			667.60
7	2	T52115-58060	SUPPORT, FR BUMPER		1.00	99.20			99.20
8	3	S52161-0K040	PIECE, RR BUMPER		10.00	4.10			41.00
9	4	T53801-58050	FENDER SUB-ASSY, FR		1.00	1259.40			1259.40
10	5	T81145-58350	UNIT, HEADLAMP		1.00	3835.60			3835.60
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 9,740.20		
			Please acknowledge receipt of vehicle 		Parts	5,902.80	GST 7.00% 681.81		
					Labour	3,837.40			
					Sublet	0.00	Less 0.00		
					Lubrication/Fluid	0.00			
					Others	0.00	Amount Due 10,422.01		

Company Copy