

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Moey Weng Foong 42 East Coast Avenue Singapore 459247 Mobile: 98764830		
			Document No.				
			0				
			Document Date				
			14/06/2021				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AGH30R	PFXLK E2	26/07/2017	SGM0900B	0	21019	67/DS/SGM0900B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTNGF3DH908010991	2ARH957429	60	Sam San Joi	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SHB1745Y ACC DATE:11/06/2021 DRIVE IN:14/06/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS				2160.00
5	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS				2360.00
6	1	T52119-58947 COVER, FR BUMPER	1.00	667.60		667.60
7	2	T52115-58060 SUPPORT, FR BUMPER	1.00	99.20		99.20
8	3	S52161-0K040 CLIPS	10.00	4.10		41.00
9	4	T53801-58050 FENDER SUB-ASSY, FR	1.00	1259.40		1259.40
10	5	T53805-58070 SHIELD SUB-ASSY,	1.00	261.60		261.60
11	6	L47749-50090 CLIP	2.00	1.80		3.60
12	7	T67001-58070 PANEL SUB-ASSY, FR	1.00	2101.90		2101.90
13	8	T81145-58351 UNIT, HEADLAMP	1.00	3835.60		3835.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			13,122.30
	Please acknowledge receipt of vehicle	Parts 8,269.90	GST 7.00% 918.56
		Labour 4,852.40	Less 0.00
		Sublet 0.00	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 14,040.86

Customer Copy