

SJR358E.

Toyota Allion. 1496CC

TP China.

Veron.

NZT2603037475.

Rear Bumper	Deformed	968	✓
Rear Bumper Clips.	Nec	30(SN)	✓
Rear Bumper Side Holder x 02	Nec	73.8 x 2 = 147.60	✓
Rear Bumper Impact Bracket x 02	Not Nec	63.2 x 2 = 126.40	X
Rear Bumper Reflector x 02	Nec	56.6 x 2 = 113.20	X
Reverse Sensor	Deformed	280(SN) → 200(SN)	
Rear End Panel	Dented	594.80	✓
Rear End Panel Top Garnish.	Deformed	265	✓
Rear End Panel Top Garnish Clips.	Nec	20(SN)	✓
Rear End Panel Sealant	Nec	60(SN)	✓
Rear End Panel Antenna Sensor	Cracked	211.70.	✓
Bootlid	Repair	951.60	X
Bootlid Lock		225.90	X
Bootlid Weatherstripe	Nec Nec	189.40	X
Toyota Logo		69.10	✓
Allion Wordings	Nec	54.10.	✓
A15 Emblem.		49.90	✓

SJR358E.

Deformed

Spere Tyre Panel Top Board 292.80 / 378.50

Taillamp x 02 RH crated 378.5 x 2 = 757

3031.50

S.N: 310

2273.62

Panel Beating

~~1000~~ 600

Spray Painting.

~~1000~~ 600

Wiring.

~~50~~ 30

To remove reverse sensor

~~100~~ 50

To remove upholstery.

~~150~~ 60 1340

To transfer bootlid fittings. 150 X.

7796.50

total: 3923.62

L/S: 3.1K.

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: