

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550
Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

No. : 06402

Date : 08-Jun-2021

PAGE : 1

Vehicle Insured : SME10SH
Accident Date : 01-Jun-2021

Our Ref : 021082 (CHINA) / CHAN

LION'S HEART STUDENT CARE PTE LTD
157F TAMARIND ROAD
#03-08
SERENITY PARK
Singapore 806110

Not Authorized
6/1/21
Penalty After 3 days

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE PC7233T =====

1 pc N/s taillamp
1 pc Rear bumper fascia

CM / W 256.90 ✓
nd / W 380.10 ✓

637.00

Less 25% : 159.25

1 pc Rear n/s fender sticker **NEC**

477.75
180.00 sn
120/12

To panel beating rear n/s fender ,
renew taillamp, rear bumper, align,
adjust & refix
to putty and spray rear n/s fender

300.00 *250*
450.00 *300*

Total : S\$ 1,407.75
=====

Singapore Dollars One Thousand Four Hundred and
Seven and Cents Seventy Five Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: