

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06402

Date : 08-Jun-2021

PAGE : 1

Vehicle Insured : SM210SH
Accident Date : 01-Jun-2021

Our Ref : 021082 (CHINA) / CHAN

LION'S HEART STUDENT CARE PTE LTD
157F TAMARIND ROAD
#03-08
SERENITY PARK
Singapore 806110

Not Withheld

11 Rm &

Recovery After Paint

3 days

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE PC7233T

1 pc N/s taillamp
1 pc Rear bumper fascia

CM / Wt 256.90 ✓
nd / Wt 380.10 ✓

637.00

Less 25% : 159.25

1 pc Rear n/s fender sticker

477.75

180.00 sn

12012

To panel beating rear n/s fender ,
renew taillamp, rear bumper, align,
adjust & refix
to putty and spray rear n/s fender

300.00

450.00

2501

3001

Total : S\$ 1,407.75

Singapore Dollars One Thousand Four Hundred and
Seven and Cents Seventy Five Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: