

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006682/KPA3Q2
Date: 28/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900166734
Claimant Vehicle No :	SJE5935A	Insured Vehicle No :	SMP5514M
Date of Loss:	10/06/2021	Nature of Claim:	TP
		Claim No:	7027515462SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE5935A	Engine No:	1NZX728656
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305058651
Reg. Date:	30/04/2008 (Man. Year: 2008)	Odometer:	214731 km
Colour:	Metallic Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Tourador 8 mm	Rear Left Side:	Tourador 8 mm
Front Right Side:	Tourador 8 mm	Rear Right Side:	Tourador 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,763.25	1,980.75	782.50	28.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,540.00	510.00	24.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,813.25	3,520.75	1,292.50	26.85
Approved Total (Overridden) (S\$)		2,800.00		

Adjuster Report

	(S\$)	4,813.25	2,800.00	2,013.25	41.83
	+ GST 7.00/7.00% (S\$)	336.93	196.00	140.93	41.83
	Nett Amount (S\$)	5,150.18	2,996.00	2,154.18	41.83
	+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
	+ Doc/Search Fee (S\$)		2.00		
	Nett Liability (S\$)		3,498.00		
	Global Sum Settlement (S\$)		3,498.00		

INSPECTION

Date of Assignment: 14/06/2021

Date Inspected: 15/06/2021

Estimated Period of Repair: 5.0 days

Inspected At: Ah Lim Motor Company (Sin Ming)
176 Sin Ming Drive #05-12, Sin Ming AutoCare
Singapore 575721**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	667.00 FL	*667.00 FL
2	1		*EMBLEM VIOS BADGE	Necessary	58.00 FL	*58.00 FL
3	1		*EMBLEM TOYOTA BADGE	Necessary	56.00 FL	*56.00 FL
4	1		*EMBLEM E BADGE	Necessary	40.00 FL	*40.00 FL
5	1		*EMBLEM SPORT BADGE	Necessary	55.00 FL	*55.00 FL
6	1		*REAR BUMPER	Buckled	496.00 FL	*496.00 FL
7	1		*REAR BUMPER SIDE RETAINER L/R	Serviceable	105.00 FL	*- FL
8	15		*REAR BUMPER CLIP	Necessary	75.00 FL	*75.00 FL
9	2		*TAILLAMP L/R	Cracked	620.00 FL	*620.00 FL
10	2		*TAILLAMP SIDE CLIP L/R	Necessary	24.00 FL	*24.00 FL
11	1		*REAR BUMPER LOWER SPOILER	Dented	550.00 FL	*550.00 FL
12	1		*TAIL END PANEL	Repair	645.00 FL	*- FL
13	1		*SET REVERSE SENSOR	Serviceable	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,611.00	2,641.00
- List Item Discount on L Items 25.00/25.00% (\$)	847.75	660.25
Total Parts (\$)	2,763.25	1,980.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND INSTALL REVERSE SENSOR	New	30.00	30.00
2	TO REPLACE REAR BOOTLID AND TRANSFER BOOT LID INNER PARTS	New	60.00	50.00
3	TO DISMANTLE AND INSTALL REAR BOOT CABIN INNER TRIM COVER AND BOARD	New	60.00	60.00
4	TO CUT ,KNOCK AND WELD TAIL END PANEL KNOCK AND REPAIR REAR FENDER BOTH SIDE AND AFFECTED AREA AND REFIT LISTED PARTS BACK SAME	New	900.00	600.00
5	TO SPRAY REAR BOOT LID-REAR BUMPER -TAIL END PANEL -REAR FENDER LH -REAR FENDER RH AND REAR BUMPER SPOILER	New	1,000.00	800.00
			Gross Labour Cost (S\$)	2,050.00
				1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >