

REF: 105 / 2 / 1



AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721
 TEL: 6456 3637 FAX: 6456 3686 Email: admin@almism.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : FAN YEW CHIONG
 29 MILTONIA CLOSE #02-19
 768062

Estimate No: MCS1900452
 Date: 10 Jun 2021
 Policy No: P10162592R02 S
 Veh Reg No: SJE5935A
 Make/Model: TOYOTA VIOS

ATTN:
 Your Ref No: SJE5935A
 Claim Type: Third Party
 Accident Date: 10/06/2021
 TP Veh Reg No: SMP5514M

*Not Notified
 11 Day @ 28000
 Resurvey After Rain 5 days*

Estimate Repair Cost to Vehicle No :SJE5935A

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BOOT LID	1 PC	667.00	✓
2 EMBLEM VIOS BADGE	1 PC	58.00	✓
3 EMBLEM TOYOTA BADGE	1 PC	56.00	✓
4 EMBLEM E BADGE	1 PC	40.00	✓
5 EMBLEM SPORT BADGE	1 PC	55.00	✓
6 REAR BUMPER	1 PC	496.00	✓
7 REAR BUMPER SIDE RETAINER L/R	1 PC	105.00	X
8 REAR BUMPER CLIP	15 PC	75.00	✓
9 TAILAMP L/R	2 PC	620.00	✓
10 TAILAMP SIDE CLIP L/R	2 PC	24.00	✓
11 REAR BUMPER LOWER SPOILER	1 PC	550.00	✓
12 TAIL END PANEL	1 PC	645.00	X
		3,391.00	
	Less 25%	847.75	2,543.25
Special Nett			
13 REVERSE SENSOR 1 SET	1 PC	220.00	X
		220.00	220.00
LABOUR			
14 TO CHECK WIRING AND INSTALL REVERSE SENSOR	1 PC	30.00	✓
15 TO REPLACE REAR BOOT LID AND TRANSFER BOOT LID INNER PARTS	1 PC	60.00	500
16 TO DISMANTLE AND INSTALL REAR BOOT CABIN INNER TRIM COVER AND BOARD	1 PC	60.00	✓
17 TO CUT, KNOCK AND WELD TAIL END PANEL KNOCK AND REPAIR REAR FENDER BOTH SIDE AND AFFECTED AREA AND REFIT LISTED PARTS BACK SAME	1 PC	900.00	6000
18 TO SPRAY REAR BOOT LID - REAR BUMPER- TAIL END PANEL - REAR FENDER LH - REAR FENDER RH AND REAR BUMPER SPOILER	1 PC	1,000.00	8000
		2,050.00	2,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

