

Date: 14.06.2021

Vehicle No: SMM6026P

Model: HONDA SHUTTLE HYBRID 1.5

Chassis: GP72003548-2018

Reg. Year: 2019

Third Party Insurer: CHINA TAIPING

Third Party Veh No: XE5782H

Date of Accident: 10.06.2021

Estimator: TING AN

Surveyor:

Not Authaird
61 Day @ 3100h
After pay
5 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BUMPER	1		<i>Rep</i> \$921.10	✓
2	REAR BUMPER SIDE BRACKET RH	1		<i>rh</i> \$35.60	X
3	REAR FENDER RH	1		<i>rh</i> \$909.20	X
4	REAR DOOR RH	1		<i>rh</i> \$843.20	X
5	REAR DOOR PROTECTIVE STICKER RH	1		<i>rh</i> \$26.90	X
6	FRONT DOOR RH	1		<i>rh</i> \$907.60	✓
7	FRONT DOOR PROTECTIVE STICKER RH	1		<i>rh</i> \$48.30	✓
8	FRONT FENDER RH	1		<i>rh</i> \$455.50	X
9	FRONT FENDER "HYBRID" EMBLEM RH	1		<i>rh</i> \$61.20	✓
10	FRONT FENDER INNER LINER RH	1		<i>rh</i> \$109.35	X
11	FRONT SIDE MIRROR ASSY RH	1		<i>cm</i> \$573.20	✓
12	FRONT SIDE MIRROR COVER RH	1		<i>cm</i> \$59.30	✓
13	FRONT BUMPER	1		<i>rh</i> \$975.20	X
14	FRONT BUMPER SIDE BRACKET RH	1		<i>rh</i> \$48.60	X
15	FRONT HEADLAMP RH	1		<i>rh</i> \$2,315.50	X
SUB TOTAL				\$8,289.75	\$2570.70
LESS 20%				-\$1,657.95	\$514.14
PARTS TOTAL				\$6,631.80	\$2056.56

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BUMPER CLIPS	1		<i>rh</i> \$50.00	✓
2	FRONT FENDER INNER LINER CLIPS	1		<i>rh</i> \$40.00	X
3	FRONT BUMPER CLIPS	1		<i>rh</i> \$50.00	X
4	REAR FENDER GLASS SEALANT	1		<i>rh</i> \$80.00	X
S/N TOTAL				\$220.00	\$50

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS & ETC. \$1,300.00 *600*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR FENDER RH, REAR DOOR RH, FRONT DOOR RH, FRONT FENDER RH, FRONT BUMPER & ETC. \$1,300.00 *1250*

Head office

6 Rung Chang Road Singapore 100143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9019 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

8B 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 3011



38101
1300
1230-11

Date: 14.06.2021
Vehicle No: SMM6026P
Model: HONDA SHUTTLE HYBRID 1.5
Chassis: GP72003548-2018
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: XE5782H
Date of Accident: 10.06.2021
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR RH INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT & REAR DOOR RH. \$240.00 *601*

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER GLASS RH, REAR FENDER GLASS SEALANT & ETC. TO EFFECT REPLACE OF REAR FENDER RH. *in* \$150.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 *201*

LABOUR TOTAL \$3,070.00 \$1930

TING AN	TOTAL	\$9,921.80
---------	--------------	-------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Finalise:
Parts: \$2056.56
Nett: \$50
Labour: \$1930
↓/s: \$4036.56 less 20% = \$3229.25
↓
\$3200