

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20003242/KPA3Q2-1
Date: 07/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0002152_01
Claimant Vehicle No :	SDJ2224H	Insured Vehicle No :	GBK525X
Date of Loss:	08/02/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0000401

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDJ2224H		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5078226
Reg. Date:	01/04/2016 (Man. Year: 2015)	Chassis No:	RU31128208
Colour:	Metallic Blue	Odometer:	102604 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	975.60	975.60	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	977.15	702.15	275.00	28.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,952.75	1,677.75	275.00	14.08
+ GST 7.00/7.00% (S\$)	136.69	117.44	19.25	14.08

Nett Amount (S\$)	2,089.44	1,795.19	294.25	14.08
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
(S\$)		2,035.19		
Liabe Amount (50.00%) (S\$)		1,017.60		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,025.05		
Global Sum Settlement (S\$)		1,000.00		

INSPECTION

Date of Assignment: 26/02/2020

Date Inspected: 27/02/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Optima Werkz Pte Ltd (HQ)
9A Serangoon North Ave 5
Singapore 554500

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDJ2224H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	175.00 F	*175.00 F
2	1		*FRONT LOWER BUMPER	Cracked	98.00 F	*98.00 F
3	1		*R/ BUMPER CORNER BRKT	Distorted	10.00 F	*10.00 F
4	1		*R/F HEADLAMP CPL	Cut	485.00 F	*485.00 F
5	1		*R/WING MOULDING	Dented	28.00 F	*28.00 F
6	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
7	1		*FRONT FENDER INNER LINER CLIPS RH	Necessary	50.00 FS	*50.00 FS
					Sub Total (\$\$)	896.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	79.60
					Total Parts (\$\$)	975.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	92.0 WU X 50.00 SGD/H	New	460.00	185.00
2	LABOUR COST 90.0 WU X 50.00 SGD/H	New	450.00	450.00
3	MATERIAL COST	New	67.15	67.15
Gross Labour Cost (\$\$)			977.15	702.15

Report was unsubmitted during this print-out.

< END OF ESTIMATES >