

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 15 Jun 2021

Preliminary Advice

Vehicle No	: GBK4875J	Accident Date	: 10/06/2021
Make	: NISSAN NV350	Policy No.	: D19MFL0005549_01
Assignment Date	: 15/06/2021	Excess	: S\$0.00
Date of Inspection	: 15/06/2021	Est. Duration of Repair	: 4
Inspection At	: EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ) 56 LOYANG WAY #06-07, LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,241.80
Revised Amount	:S\$	5,949.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,949.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	21,884.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,116.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :