

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 17 June 2021 12:21 pm
To: Jessie Ong; ezel@panpacificleasing.com.sg; andrew.goh@panpacificleasing.com.sg; ppemclaims@gmail.com
Cc: SUR
Subject: RE: III-OD GBK 4875J DOA: 10/06/2021

Dear Sir/Madam,

Please be informed that the excess of GBK 4875J is \$1,500.00.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, 17 June 2021 10:36 am
To: Jessie Ong <jessie.ong@panpacificleasing.com.sg>; ezel@panpacificleasing.com.sg; andrew.goh@panpacificleasing.com.sg; ppemclaims@gmail.com
Cc: SUR <sur@lkkauto.com>
Subject: III-OD GBK 4875J DOA: 10/06/2021

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **GBK 4875J at repair cost not more than \$2,000.00 on Lump Sum basis (Excess TBA)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey of before paint for all panels and parts.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)