

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 7552K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT O/S HEADLAMP	DAMAGED	1,548.30	1,170.00
1	FRONT GRILLE	DAMAGED	363.99	363.99
1	FRONT GRILLE LOGO	NECESSARY	96.70	96.70
1	FRONT BUMPER	DAMAGED	1,745.60	981.00
1	FRONT BUMPER O/S FOG LAMP	SERVICEABLE	269.92	-
1	FRONT BUMPER O/S FOG LAMP COVER	DAMAGED	194.00	115.00
1	FRONT BUMPER INNER SPONGE	DAMAGED	163.77	118.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	471.90	-
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	259.80	122.00
1	FRONT BUMPER TOP BEAM	SERVICEABLE	182.00	- n
1	FRONT O/S FENDER	TO REPAIR SEE LABOUR	1,032.50	-
1	FRONT SUPPORT PANEL TOP COVER	SERVICEABLE	320.00	·
	LESS 25% DISCOUNT		-1,662.12	-741.67
			4,986.36	2,225.02
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
			60.00	30.00
	LABOUR			
	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSING.		80.00	30.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		60.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT O/S FENDER.		1,080.00	250.00

Report Ref No. CS3/LPC21004585/Etf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
			2,220.00	710.00
	GRAND TOTAL		7,266.36	2,965.02

RECOMMENDED COST OF LUMP SUM REPAIRS	The Land of the Control	2,350.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/LPC21004585/Etf3e2-1

les

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report,

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.