



24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Tan Bee Choo
C/o: Galaxy Auto Care Pte Ltd
13 Kaki Bukit Road 4
#01-23 Bartley Biz Centre, Singapore 417807

Date : 20 April 2021
Our ref : GAL/04/2101/TP

Accident Date : 09 April 2021
Inspection Date : 12 April 2021
Repairer Name : Galaxy Auto Care Pte Ltd
13 Kaki Bukit Road 4
#01-23 Bartley Biz Centre, Singapore 417807

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No	: SKG 7552 K	Year / Capacity	: 2009 / 2362 cc
Make / Model	: Toyota Estima	Colour	: Gold
Chassis No	: ACR507059302	Mileage	: 191830
Engine No	: 2AZF147683		

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Hablead	225/55 R17	5 mm	Sport
Front Offside	: Hablead	225/55 R17	5 mm	Sport
Rear Nearside	: Hablead	225/55 R17	5 mm	Sport
Rear Offside	: Hablead	225/55 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front o/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 47 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$4,300.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No.: SKG 7552 K

Our Ref No.: GAL/04/2101/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front o/s headlamp	Damage	\$ 1,548.30	\$ 1,548.30
1	Front grille	Damage	\$ 363.99	\$ 363.99
1	Front grille logo	Necessary	\$ 96.70	\$ 96.70
1	Front bumper	Damage	\$ 1,745.60	\$ 1,745.60
1	Front bumper o/s fog lamp	Damage	\$ 269.92	\$ 269.92
1	Front bumper o/s fog lamp cover	Damage	\$ 194.00	\$ 194.00
1	Front bumper inner sponge	Damage	\$ 163.77	\$ 163.77
1	Front bumper reinforcement	Intact	\$ 471.90	
2	Front bumper side retainers	Necessary	\$ 259.80	\$ 259.80
1	Front bumper top beam	Damage	\$ 182.00	\$ 182.00
1	Front o/s fender	Repair	\$ 1,032.50	
1	Front support panel top cover	Damage	\$ 320.00	\$ 320.00
			\$ 6,648.48	\$ 5,144.08
			<i>Less 25%</i>	<i>\$ 1,662.12</i>
Total Cost - List Items			\$ 4,986.36	\$ 3,858.06

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00
Total Cost - Special Nett items			\$ 60.00	\$ 60.00

Total cost of parts

\$ 5,046.36	\$ 3,918.06
--------------------	--------------------

Vehicle Registration No.: SKG 7552 K

Our Ref No.: GAL/04/2101/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 5,046.36	\$ 3,918.06

LABOUR

1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00	\$ 50.00
2	To apply undercoating on repaired and replaced panel.	\$ 60.00	\$ 30.00
3	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00
4	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00

GRAND TOTAL

\$ 7,266.36	\$ 5,408.06
--------------------	--------------------

Vehicle Registration No.: SKG 7552 K

Our Ref No.: GAL/04/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 4,300.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser