



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2107957

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 18/11/2021
Reference CC4/LPC21006693/Bps3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 8636G
Insured Veh. SKU 4760Y
Claim No. 20/21/21/VP05/024655
Policy No. Z20VP05027275
Accident Date 13/06/2021
Inspection Date 16/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21006693/Bps3q2 Date: 18/11/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 4760Y	Veh. Inspected	SMJ 8636G	
Policy No.	Z20VP05027275	Coverage (\$)	0.00	
Claim No.	20/21/21/VP05/024655	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	15/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP51339851	Colour	WHITE	
Odometer	40491 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	5 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2021	Inspection Date	16/06/2021	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 8636G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RH	DENTED	368.50	368.50
1	FRONT FENDER LOGO 'HYBRID'	NECESSARY	58.00	58.00
1	FRONT FENDER COWLING RH	BROKEN	91.50	75.00
8	FRONT FENDER COWLING CLIP	NECESSARY	28.00	20.00
1	FRONT FENDER STAND GARNISH RH (NPA)	NOT DAMAGED	-	-
1	FRONT DOOR RH	DENTED	757.20	757.20
1	SET FRONT DOOR RH STICKER	NECESSARY	35.80	25.00
1	FRONT DOOR RH HINGE BOTTOM	NOT DAMAGED	48.60	-
1	FRONT DOOR RH CHECK	NOT DAMAGED	48.60	-
1	FRONT DOOR RH RUBBER FRONT	NOT DAMAGED	14.30	-
1	FRONT DOOR RH RUBBER BOTTOM	NOT DAMAGED	18.50	-
1	FRONT DOOR RH WINDOW GLASS	NOT DAMAGED	417.20	-
1	FRONT DOOR RH WINDOW GEAR WITH MOTOR	NOT DAMAGED	416.50	-
1	REAR DOOR RH	DENTED	799.50	736.20
1	REAR DOOR RH STICKER	NECESSARY	25.00	25.00
1	REAR DOOR RH HINGE BOTTOM	NOT DAMAGED	32.70	-
1	REAR DOOR RH CHECK	NOT DAMAGED	40.50	-
1	REAR DOOR RH RUBBER FRONT	NOT DAMAGED	46.80	-
1	REAR DOOR RH RUBBER REAR	NOT DAMAGED	19.50	-
1	REAR DOOR RH RUBBER BOTTOM	NOT DAMAGED	15.40	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	529.90	-
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	18.70	18.70
12	REAR BUMPER CLIP	NECESSARY	42.00	30.00
1	FRONT WHEEL HUB RH	NOT DAMAGED	138.20	-
1	FRONT WHEEL BEARING RH	NECESSARY	168.00	168.00
1	REAR WHEEL HUB AND BEARING RH	NOT DAMAGED	306.60	-
1	FRONT DOOR RH LOCK	NOT DAMAGED	262.30	-
1	REAR DOOR RH LOCK	NOT DAMAGED	210.00	-
	LESS 20% DISCOUNT		-991.56	-456.32
			3,966.24	1,825.28

Report Ref No. CC4/LPC21006693/Bps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
2	SPORT RIM -RHF & RHR (LOCAL REPAIR) (SN)	CUT (1 PCS ONLY)	200.00	200.00
1	TYRE -RHF & RHR (NPA) (SN)	NOT DAMAGED	-	-
			200.00	200.00
	<u>LABOUR</u>			
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR /FACILITATE REPAIR RHF & RHR .		240.00	80.00
	TO REMOVE AND REINSTALL CUSHIONS ,SEATS ,BACKREST ,INNER TRIM, GARNISH ,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS ,RH.	NOT NECESSARY	180.00	-
	TO DISMANTLE ,REPLACE AND REINSTALL UNDERCARRIAGE RHF & RHR.		180.00	80.00
	TO REMOVE AND REINSTALL /REPLACE REAR BUMPER SENSORS.	NOT NECESSARY	60.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS .	NOT NECESSARY	80.00	-
	TO DISMANTLE ALL DAMAGED PARTS .TO KNOCK & REPAIR ROCKER PANEL RH ,CENTRE PILLAR RH ,REAR FENDER RH ,INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		1,000.00	600.00
	TO SPRAY FRONT FENDER RH ,FRONT DOOR RH ,REAR DOOR RH,ROCKER PANEL RH ,CENTRE PILLAR RH ,REAR FENDER RH ,REAR BUMPER .		1,200.00	1,000.00
			3,020.00	1,760.00
GRAND TOTAL			7,186.24	3,785.28
RECOMMENDED COST OF REPAIR SUM				3,785.00

Report Ref No. CC4/LPC21006693/Bps3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 8636G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 8636G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

