

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

16/6/21  
1 pm  
**SURVEYOR COPY**

M/S : KOH TAIWEI JOHN  
75 ANCHORVALE CRESCENT #10-11

SINGAPORE 544662

ATTN:

Estimate No: MC1901991  
Date: 14 Jun 2021  
Policy No: P10527363R00  
Veh Reg No: SMJ8636G  
Make/Model: HONDA FIT HYBRID 1.5  
AUTO

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 13/06/2021  
TP Veh Reg No: SKU4760Y

## Estimate Repair Cost to Vehicle No :SMJ8636G

2019

| Description                                  | Quantity | List Price    | Amount         |
|----------------------------------------------|----------|---------------|----------------|
|                                              |          | S\$           | S\$            |
| <b>SPARE PARTS</b>                           |          |               |                |
| 1 FRONT FENDER RH                            | 1 PC     | ✓ 368.50      | DDV            |
| 2 FRONT FENDER LOGO "HYBRID"                 | 1 PC     | ✓ 58.00       | NECV           |
| 3 FRONT FENDER COWLING RH                    | 1 PC     | ✓ 91.50       | BRV            |
| 4 FRONT FENDER COWLING CLIP                  | 8 PC     | 20.00 28.00   | NECV           |
| 5 FRONT FENDER STAND GARNISH RH -CHECK PRICE | 1 PC     | 0.00          |                |
| 6 FRONT DOOR RH                              | 1 PC     | ✓ 757.20      | DDV            |
| 7 FRONT DOOR RH STICKER SET                  | 1 PC     | 25.00 35.80   | NECV           |
| 8 FRONT DOOR RH HINGE BOTTOM                 | 1 PC     | 48.60         | NDX            |
| 9 FRONT DOOR RH CHECK                        | 1 PC     | 48.60         | NDX            |
| 10 FRONT DOOR RH RUBBER FRONT                | 1 PC     | 14.30         | NDX            |
| 11 FRONT DOOR RH RUBBER BOTTOM               | 1 PC     | 18.50         |                |
| 12 FRONT DOOR RH WINDOW GLASS                | 1 PC     | 417.20        | NDX            |
| 13 FRONT DOOR RH WINDOW GEAR WITH MOTOR      | 1 PC     | 416.50        | NDX            |
| 14 REAR DOOR RH                              | 1 PC     | 736.20 799.50 | DDV            |
| 15 REAR DOOR RH STICKER                      | 1 PC     | ✓ 25.00       | NECV           |
| 16 REAR DOOR RH HINGE BOTTOM                 | 1 PC     | 32.70         | NDX            |
| 17 REAR DOOR RH CHECK                        | 1 PC     | 40.50         | NDX            |
| 18 REAR DOOR RH RUBBER FRONT                 | 1 PC     | 46.80         | NDX            |
| 19 REAR DOOR RH RUBBER REAR                  | 1 PC     | 19.50         | NDX            |
| 20 REAR DOOR RH RUBBER BOTTOM                | 1 PC     | 15.40         | NDX            |
| 21 REAR BUMPER                               | 1 PC     | 529.00        | CUT X R        |
| 22 REAR BUMPER SIDE RETAINER RH              | 1 PC     | ✓ 18.70       | NECV           |
| 23 REAR BUMPER CLIP                          | 12 PC    | 30.00 42.00   | NECV           |
| 24 FRONT WHEEL HUB RH                        | 1 PC     | 138.20        | NDX            |
| 25 FRONT WHEEL BEARING RH                    | 1 PC     | ✓ 168.00      | NECV           |
| 26 REAR WHEEL HUB AND BEARING RH             | 1 PC     | 306.60        | NDX            |
| 27 FRONT DOOR RH LOCK                        | 1 PC     | 262.30        | NDX            |
| 28 REAR DOOR RH LOCK                         | 1 PC     | 210.00        | NDX            |
|                                              |          | 2298.10       | 4,957.80       |
| Less 20%                                     |          | 459.62        | 991.56         |
|                                              |          | 1838.48       | 3,966.24       |
| <b>Special Nett</b>                          |          |               |                |
| 29 SPORT RIM - RHF & RHR -CHECK PRICE        | 2 PC     | 200.00        | 0.0000 CUT X R |
| 30 TYRE - RHF & RHR -CHECK PRICE             | 2 PC     | 0.0000        | NDX            |
|                                              |          | 0.00          | 0.00           |
| <b>LABOUR</b>                                |          |               |                |

local repair (RHF) 2PC 200.00  
ND X 0.0000

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

M/S : KOH TAIWEI JOHN  
75 ANCHORVALE CRESCENT #10-11

SINGAPORE 544662

ATTN:

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 13/06/2021  
TP Veh Reg No: SKU4760Y

Estimate No: MC1901991  
Date: 14 Jun 2021  
Policy No: P10527363R00  
Veh Reg No: SMJ8636G  
Make/Model: HONDA FIT HYBRID 1.5  
AUTO

## Estimate Repair Cost to Vehicle No :SMJ8636G

| Description                                                                                                                                                               | Quantity             | List Price                  | Amount       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|-----------------------------|--------------|
|                                                                                                                                                                           |                      | S\$                         | S\$          |
| 31 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.                                                                                                                                | 1 PC                 | <del>80.00</del> 60.00      |              |
| 32 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR. RH & RHR                                 | 2 PC                 | <del>80.00</del> 240.00     |              |
| 33 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS. RH                                            | 1 PC                 | <del>180.00</del> N/A       |              |
| 34 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE. RH & RHR                                                                                                            | 1 PC                 | <del>80.00</del> 180.00     |              |
| 35 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.                                                                                                                   | 1 PC                 | 60.00                       |              |
| 36 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.                                                                                                                          | 1 PC                 | <del>80.00</del> N/A        |              |
| 37 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR ROCKER PANEL RH, CENTRE PILLAR RH, REAR FENDER RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. | 1 PC                 | <del>600.00</del> 1,000.00  |              |
| 38 TO SPRAY FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, ROCKER PANEL RH, CENTRE PILLAR RH, REAR FENDER RH, REAR BUMPER                                                  | 1 PC                 | <del>1000.00</del> 1,200.00 |              |
|                                                                                                                                                                           | 1888.00              | 3,020.00                    | 3,020.00     |
|                                                                                                                                                                           | Total                |                             | S\$ 6,986.24 |
|                                                                                                                                                                           | Add GST @ 7%         |                             | 489.04       |
|                                                                                                                                                                           | Total Amount Payable |                             | S\$ 7,475.28 |

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED SEVENTY FIVE AND CENTS TWENTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

survey  
16/6/2021

1334

TG Lim

9736577 TG Lim

Part by Part repair

COR 3918.48